

E3.I Cayenne DME P242100 – Fuel Tank Isolation Valve for Tank Ventilation System - Stuck Open

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	As of 2019 up to 2023	9YAAE1 9YACH1 9YBAE1 9YBCH1	N/A	N/A

Revision History

Revision	Release Date	Changes
0	April 5, 2024	Original document
1	July 29, 2024	Update of Vehicles Affected
2	August 20, 2024	Update of Vehicles Affected, Update of part number 11)

Condition

Customer complains of the check engine light on. Workshop scanned vehicle and found DME fault P242100 - Fuel Tank, Isolation valve for tank ventilation system stuck open.


Technical Background

Carbon deposits from the carbon canister may impair the sealing function of the sealing membrane in the tank ventilation system.

Service Information

Please replace these four components shown in yellow below:

1)	PAB 201 801 C	Evaporative Emission Canister
11)	PAD 201 559	Pressure Regulator
16)	PAB 201 183	Breather Line
24)	PAB 201 999	Vent Hose



Warranty

For documentation and warranty invoicing, enter the working position and PCSS encryption specified below in the warranty claim:

APOS	Labor operation	I No.
20251900	Carbon canister remove and reinstall	
20231960	Tank vent remove and reinstall	
20381920	Supply line remove and reinstall	

Advanced Technical Information

Bulletin #: 2412.2

Part ID: 2026

2

PCSS encryption:

Location (FES5)	20660	Fuel Pump
Damage type (SA4)	5061	Pressure too Low

Search Items

Cayenne, Fuel Tank, Ventilation, Isolation Valve, 9YA, 9YB, Low Pressure, Pressure too Low, Not Airtight

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.