

Technical Service Bulletin (TSB)

Flash: Powertrain Control Module (PCM) Updates

REFERENCE:	TSB: 18-069-24 GROUP: 18 - Vehicle Performance	Date:	September 7, 2024	REVISION:	18-015-23
VEHICLES AFFECTED:	2023 (WL) Jeep Grand Cherokee / Grand Cherokee L This bulletin applies to vehicles equipped with a 5.7L V8 Hemi MDS VVT (Sales Code EZH).			MARKET APPLICABILITY: ☐ NA☐ MEA ☐ SA☐ **IAP** ☐ EE☐ **CH**	
CUSTOMER SYMPTOM:	**Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Code (DTC): • **P2066 - Fuel Level Sensor 2 Performance.** • C053D - Brake Pressure Sensor 1 Performance. **Customers may experience one or more of the following: • When the driver attempts to override the Electric Park Brake (EPB) while it remains engaged due to an unbuckled seatbelt in Drive or Reverse, the high torque request with the park brake engaged may lead to a damaged or broken Rear Drive Unit (RDU). • MIL illuminates when fueling the vehicle while the engine is running. • Lower fuel economy reported by the Instrument Panel Cluster (IPC). • Rough engine idle during warm up. • Engine shuts off while idling in park.**				
CAUSE:	PCM software				

This bulletin supersedes Technical Service Bulletin (TSB) 18-015-23, date of issue February 03, 2023, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include the addition of a DTC, new customer symptoms, additional markets, an updated RSU statement, a new LOP, updated claims data statement and an updated repair procedure step.

****This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-031, date of issue February 03, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. ****

REPAIR SUMMARY:

This bulletin involves reprogramming the PCM with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-06-J7	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1 - Engine Repair and Performance	0.3 Hrs.
Failure Code	CC	Customer Concern	

****The dealer must use failure code CC with this Technical Service Bulletin.**

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes a symptom/condition or if the technician finds a DTC listed above, perform the repair procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	—	—

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. **If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.**
2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.