



SSM 52941 2020-2025 Police Interceptor Utility - Hybrid - Illuminated MIL With DTC P061B Stored In The PCM - Service Tips

Some 2020-2025 Police Interceptor Utility hybrid vehicles may exhibit multiple warning messages, various driveability concerns and/or an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P061B stored in the powertrain control module (PCM). This may be due to the incorrect installation of additional police equipment. Equipment should only use the provided rear power access point and not the 12V cranking/auxiliary batteries. The vehicle will go to sleep after the ignition key is removed and is not designed to power equipment when the vehicle is not running. If equipped, the Police Engine Idle feature can be used to allow the vehicle to securely remain idling and to power equipment, refer to the Owner's Manual.

For general upfitter installation guidelines, refer to:

- (a) Professional Technician System (PTS) website > Service Tips > Police Interceptor Utility - Modifier Guide, or
- (b) Ford Pro™ at this website: <https://www.fordpro.com/> > Resources > Body Builder Advisory Service (BBAS) > Publications > Police Modifier Guide.