



Technical Service Bulletin

01 Engine: engine control unit - engine warning lamp on - P016900 DFCC 45233 incorrect fuel detection - 4-cyl. 2.0 TFSI

01 24 40 2075261/1 September 30, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5 Sportback and Q5	2022 – 2023	All	4-cyl 2.0 TFSI

Condition

Customer States:

- Engine warning lamp on.

Workshop findings:

- The following DTC P016900 with symptom code DFCC 45233 are logged in ECM -J623-, (address word 0001). It is not possible to erase entry. Guided Fault Findings conclude that the control unit should be replaced.

Technical Background 1

Under analysis.

Production Solution

Not applicable.

Service

Follow the instructions in Guided Fault Findings but do not replace the ECM!

A defined sequence of steps is required to erase the entry.

To erase the entry, carry out the following procedure:

- Switch ignition on (Terminal 15).
- Erase event memory.
- Start engine as long as ignition is on (Terminal 15).
- Switch ignition/engine off.
- Switch ignition on (Terminal 15).
- Erase event memory again.
- Entry is erased!**



Technical Service Bulletin

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2075261/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2075261**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.