



# Technical Service Bulletin

## 20 Repair Authorization - DTC P008700 or P014800 Stored in ECM

20 24 72 2075223/1 September 17, 2024.

| Model(s)                                                    | Year        | VIN Range | Vehicle-Specific Equipment |
|-------------------------------------------------------------|-------------|-----------|----------------------------|
| A4, A4 allroad,<br>A5, A5 Cabriolet,<br>and A5<br>Sportback | 2022 – 2024 | All       | Not Applicable             |

### Condition

#### Customer states:

- MIL/ exhaust emission lamp lights up in the instrument cluster.

OR

- Drive system: malfunction** lamp lights up in the instrument cluster.

#### Workshop findings:

One or more of following DTCs MUST be stored in the engine control module ECM, J623 (address word 001):

- P008700** (Fuel Rail/System Pressure - Too Low) with **symptom code** 15058.
- P008700** (Fuel Rail/System Pressure - Too Low) with **symptom code** 15059.
- P014800** (Fuel Delivery Error) with **symptom code** 40466.

### Technical Background 1

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

### Production Solution

No changes to production have been made, as no issue has been identified.



# Technical Service Bulletin

---

## Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

Verify the condition.

If the vehicle is within the New Vehicle Limited Warranty, please perform the following steps as per the ELSA Repair Manual and contact a TAC consultant with the results and photos before proceeding. Please attach the DTC and diagnostic log and results from tests as photos to the TAC ticket/TAC Web Ticket.

- “Checking fuel delivery rate”.
- “Pressure test in the fuel supply line”.
- “Checking residual pressure”.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2075223**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.