



Technical Service Bulletin

91 ACC inop / PreSense Malfunction, DTC B200FF0 (sym 196672) in 0013

91 24 53 2068008/2 September 18, 2024. Supersedes Technical Service Bulletin Group 91 number 22-27 dated September 14, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2021 - 2024	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Warranty</i> (Updated Claim Types)
1	09/14/2022	Initial publication

Customer states:

Various driver assist systems are inoperative.

The following messages are displayed in the instrument cluster:

- Distance warning: currently unavailable. See owner's manual.
- Audi pre sense: fault. Please contact the workshop.

Workshop findings:

The following DTC may be stored in the control module for Distance Regulation –J428– (diag. addr. 0013)

- DTC B200FF0:** Internal Malfunction (**symptom 196672**).

Technical Background 1

An internal diagnosis malfunction causes the DTC to enter erroneously.

Production Solution

Not applicable.



Technical Service Bulletin

Service

1. Clear the DTCs that have been stored in the vehicle.
2. Cycle the ignition.
3. The driver assist systems should be available again after clearing DTCs and the instrument cluster messages (see Condition) should disappear.

NOTICE

Claims for replaced parts will not be reimbursed.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9163		
Damage Code:	0039		
Labor Operations:	GFF	0150 0000	Time stated on the diagnostic protocol
	Charge Battery	2706 8950	See SRT with associated operations
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2068008/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2068008**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.