



Technical Service Bulletin

91 MIB3: Volume control not working - U11B900

91 24 67 2072873/4 October 16, 2024. Supersedes Technical Service Bulletin Group 91 number 24-08 dated May 7, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, S3, RS 3, e-tron GT, RS e-tron GT, Q4 e-tron, and Q4 Sportback e-tron	2022 – 2025	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header (added MY25)
3	05/07/2024	Revised header (added customer codes) Revised <i>Service</i> (updated reset time) Revised <i>Warranty</i> (updated labor ops)
2	02/23/2024	Revised header (updated part number filter) Revised <i>Warranty</i> (updated labor ops)

Customer states:

- The touch-operated volume control in the center console is not working.
- The volume control, as well as the skip buttons are inoperable.

Workshop findings:

The following DTC and symptom code is stored in *Information Electronics name -J794-*, (address word 005F):

- DTC U11B900:** Volume control no communication (active/static).

Technical Background 1

Not applicable.



Technical Service Bulletin

Production Solution

Not applicable.

Service

Perform a terminal 30 reset for volume regulator E67:

Remove the relevant fuse for at least 30 seconds and then, replace it.

After the terminal 30 reset, check whether the volume control is working.

If it is working, no further repairs are required.

If the volume control is not working after the terminal 30 reset, replace volume regulator E67.

NOTICE

Refer to the current wiring diagram in ELSA for the relevant fuse.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9110		
Damage Code:	0010		
Labor Operations:	Check multimedia system operating unit (KL30 reset)	9195 0199	20 TU (without parts replacement) 5 TU (with parts replacement)
	Remove and install multimedia system operating unit	9195 19XX	See SRT with associated operations



Technical Service Bulletin

	Charge battery	2706 8950	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2072873/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Driver Volume Control (E67) (if required)	01

Additional Information

All parts and service references provided in this TSB (**2072873**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.