



Technical Service Bulletin

93 PSS Q8 e-tron: Charging flap module without search illumination; P33E300; B1A8AF3

93 24 27 2073481/4 November 4, 2024. Supersedes Technical Service Bulletin Group 93 number 24-61 dated June 28, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8 e-tron, Q8 Sportback e-tron; SQ8 e-tron, and SQ8 Sportback e-tron	2024 – 2025	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised <i>Service</i> (updated ETA)
3	06/28/2024	Revised <i>Condition</i> (Updated workshop findings)
2	05/31/2024	Revised header (Corrected Elsa display issue)

This bulletin only applies to Q8 e-tron variants with a single charging port.

Customer states:

- The orientation light in the charging flap module does not work.

Workshop findings:

The search illumination in the charging flap module does not work if the vehicle is only equipped with one charge flap module as standard.

The following DTC or DTCs may be logged in *the high-voltage battery charger -J1050-*, (address word 00C6):

- DTC P33E300: Charging socket B communication fault.**
- DTC B1A8AF3: Charge door 2 LIN actuator communication malfunction**

Technical Background 1

The orientation light in the charging flap module aims to help the customer correctly plug in the charging connector in dark conditions. A second charging flap module can be ordered as an option on the Q8 e-tron.



Technical Service Bulletin

If the vehicle is only equipped with single charging flap module the orientation light does not work. An error in the OBC (00C6) software means that the orientation light LED is not activated when the vehicle is equipped with only one charging flap module.

If the vehicle is equipped with both charging flap modules (left and right) the lighting is active and functions as designed.



Figure 1: Vehicle with functioning orientation light in the charging flap module.



Figure 2: Vehicle with a non-functioning orientation light in the charging flap module.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2024 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2073481**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.