



Technical Service Bulletin

93 Repair authorization - e-tron/Q8 e-tron charging door; P33E200, P31D000

93 24 39 2076132/1 November 27, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron and e-tron Sportback	2023	All	Not Applicable
Q8 e-tron, Q8 e-tron Sportback, SQ8 e-tron, and SQ8 e-tron Sportback	2024		

Condition

Customer states:

Charge door is not opening.

Workshop findings:

One or more of the following DTCs may be stored in the High-voltage battery charger, J1050 (address word 00C6):

- **P33E200:** Charging socket B electrical error.
- **P31D000:** Charge cover B recognition cover locking electrical error.

Technical Background 1

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition. Verify the condition.

Please fill out the worksheet in the attached documents and save it as a .pdf.



Technical Service Bulletin

If the vehicle is within the New Vehicle Limited Warranty, contact the Technical Assistance Center (TAC) before proceeding. Please attach the DTC and diagnostic log and the to the TAC Web Ticket.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2076132**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.