



Technical Service Bulletin

19 Red coolant warning lamp on, DTCs P218100, P017B00, P017C00, and/or P017E00 are stored in the ECM

19 24 73 2062951/4 December 3, 2024. Supersedes Technical Service Bulletin Group 19 number 23-41 dated September 7, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019 – 2020	All	Not Applicable
	2021	000001 – 007769	
S8	2020	All	
	2021	000001 – 007769	
SQ7	2020	All	
	2021	000001 – 015609	
SQ8	2020	All	
	2021	000001 – 010457	
RS Q8	2020	All	
	2021	000001 - 011352	
RS 6 Avant, and RS 7	2021	900001 - 901935	

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised <i>Condition</i> (updated TSB reference) Revised <i>Warranty</i> (Updated Claim Types, Labor Operations)
3	09/07/2024	Revised <i>Condition</i> (Updated workshop findings)
2	10/21/2022	Revised <i>Warranty</i> (Updated Labor Ops)

Customer states:

- Red coolant warning lamp is illuminated in the instrument cluster.


Workshop findings:



Technical Service Bulletin

One or more of the following DTCs **must** be stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P218100** (Malfunction in cooling system).
- **DTC P017B00** (Cylinder head temperature sensor implausible signal).
- **DTC P017C00** (Cylinder head temperature sensor short circuit to ground).
- **DTC P017E00** (Cylinder head temperature sensor open circuit/loose contact).



NOTICE

If DTCs P1BB400 or P218100 are also stored in the ECM, please also review TSB 2075878 to determine the appropriate action.

Technical Background 1

Damage to the O-ring of the temperature sensor can cause water intrusion inside the plastic housing of the coolant temperature sender G407 (cylinder head temperature sensor). The moisture can damage the sensor element. The loss of function can be sporadic.

Production Solution

Improved part in production.

Vehicle type	Chassis number	Vehicle production date
A8	WAURSCF88MN007770	27/10/2020
S8	WAURSEF82MN005380	07/10/2020
SQ8	WA1CWBF17MD010458	30/09/2020
SQ7	WA1VWBF75MD015610	30/09/2020
RS 6/7	WUAPCBF25MN901936	14/10/2020
RS Q8	WUARRDF11MD011353	06/10/2020

Service

1. Work through Guided Fault Finding.



Technical Service Bulletin

2. It is **very important** to also check whether the o-ring located directly on the tip of the coolant temperature sender G407 is visibly damaged and/or pinched (Figure 1).



Figure 1. O-ring is pinched.

3. Replace the G407 if the o-ring is damaged and/or pinched.

Warranty

Claim Type:	• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1978		
Damage Code:	0040		
Labor Operations:	Remove and install temperature sender	1978 19XX	See SRT with associated operations
	GFF	0150 0000	Time stated on the diagnostic protocol
	Charge battery	2706 8950	See SRT with associated operations



Technical Service Bulletin

Claim Comment:	As per TSB 2062951/4
-----------------------	----------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Coolant temperature sender G407 (if necessary)	01

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)

Additional Information

All parts and service references provided in this TSB (**2062951**) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.