ATTENTION:
GENERAL MANAGER ❑
PARTS MANAGER ❑
CLAIMS PERSONNEL ❑
SERVICE MANAGER ❑

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2017 Subaru of America, Inc. All rights reserved.

SUBARU

QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2010-2014MY Legacy and Outback
NUMBER: 06-58-17
SUBJECT: Electronic Parking Brake (EPB) Inoperative / DTC C0251
DATE: 02/16/17

INTRODUCTION:

This bulletin announces a new replacement EPB actuator assembly to address DTC C0251. In isolated cases, the automatic calibration function of the EPB actuator may not always occur when turning the ignition on. As a **temporary** result, the EPB may not function, the brake system warning lamp will flash to alert the driver and DTC C0251 will be stored in memory. The EPB will resume normal operation on the next key cycle.

PART INFORMATION:

Description	Part Number	Applicability
ACTUATOR ASSY- EPB	26002AJ01D	2010-2012MY
	26002AJ02C	2013 & 2014MY
SELF-LOCKING NUT	023508000	ALL (Qty. 4 Req'd.)

Combination Meter Brake System Warning Lamp



SERVICE PROCEDURE / INFORMATION:

When replacing the EPB2 Actuator assembly, follow the complete Service Procedure in the applicable Service Manual.

IMPORTANT NOTES:

- As part of the service procedure, the fuel tank protector will need to be removed. The 4 self-locking nuts securing the protector are **One-Time Use** items and must be replaced at re-assembly. The torque specification for these nuts is 9 Nm (6.6 foot-lbs.).
- After EPB actuator assembly installation is complete, the Force Sensor Calibration Mode must be performed with the Subaru Select Monitor following the procedure in the applicable Service Manual.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.
Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT
ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
EPB ACTUATOR / CM ASSEMBLY R&R	B544-251	1.0	SDP-43
CM VERSION UPDATE AT TIME OF REPLACEMENT	C860-118	0.3	
EPB TESTING and DIAGNOSIS	C544200	0.4	

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.