Bulletin No.: PIC5942
Date: Dec-2013

Service Bulletin

PRELIMINARY INFORMATION

Subject: **Diagnostic Tip - ABS/Traction Control Indicators On No Communication With The EBCM**

Models: **2014 Buick Verano**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment that the ABS/Traction Control Indicators are on in the IPC.

During initial scan for diagnostic codes you may find that there is a U0415 stored and notice that you cannot communicate with the K17 Electronic Brake Contro Module (EBCM).

There is currently an issue with GDS2 which is not allowing the Scan Tool to communicate with the K17 Electronic Brake Control Module EBCM.

Recommendation/Instructions

For a current work around, build the vehicle as a 2013 Model Year Buick Verano. This will allow the Technician to communicate with the K17 Electronic Brake Control Module (EBCM) and address any current DTCs that might be stored.

Engineering has been made aware of this issue and is working to correct the concern.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION