Bulletin No.: PIP5240B
Published date: 02/1/2017

Preliminary Information

PIP5240B Mil On With DTC P0171 And / Or P1101

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2013 - 2015	All	All	(LUV) 1.4L	All
Chevrolet	Trax	2013 - 2015	Canada	Only	(LUV) 1.4L	All
Chevrolet	Trax	2015	US	Only	(LUV) 1.4L	All

Supersession Statement


This PI was superseded to update Model Years. Please discard PIP524B.
The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A technician may encounter a DTC P0171 And / Or P1101 set current or in history.

Recommendations / Instructions

If SI diagnostics do not isolate the cause of the concern, inspect the ID code on the Air Cleaner Housing. (See photo below).



The correct application for the 2013-2015 Buick Encore and 2013-2015 Chevrolet Trax will have an ID code of ACD and will be fitted with a Hydro Carbon Absorber as shown below.



If the Hydro Carbon Absorber is missing, or the ID code is other than ACD, replace the Air Cleaner Housing with the latest listing in the Electronic Parts Catalog.

If the Hydro Carbon Absorber is present and the ID code is ACD, refer back to current SI diagnostics.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

©2016 General Motors. All Rights Reserved.