Connection offline

Technical Service Bulletin

Transaction No.: **2079998/5**

35 Gearbox: drive system fault in instrument cluster, DTC P071100 symptom 20756 - diagnostic address 0002

Release date: Sep 28, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
A5, S5 (FU), Q5, Q5 Sportback e-tron, SQ5, SQ5 Sportback e-tron (GU)	2025	All up to CW 36/25	00A5 - Front sensor for driver assistance systems			
			Software part number	**Software version**	**Hardware part number**	**Hardware version**
			*	0250	*	*
			*	0295	*	*

REVISION HISTORY		
Revision	**Date**	**Purpose**
5	-	Revised *Condition* (Updated verbiage) Revised *Production solution* (Updated verbiage) Revised *Service* (Updated instructions) Updated *Warranty* (Updated labor operations) Updated *Additional Information* (Updated verbiage)
4	01/30/2026	Revised header (Added software version)
3	12/18/2025	Revised header (Added Model Year) Revised *Warranty* (Updated Labor Operations)

Customer states:

- The drive system fault warning lamp lights up in the dash panel insert.

and/or

- There is no direct customer complaint.
- The event memory entry specified in the workshop findings is found in gearbox electronics control unit J217 in connection with a different complaint.

Workshop findings:

The following event memory entry (static/intermittent) is logged in the gearbox electronics control unit (diagnostic address 0002):

- **P071100:** “Transmission Fluid Temperature Sensor "A" Circuit Range/Performance” with symptom code 20756

and subsequent entry

- **P270800:** “Solenoid Valve 6 is sticking on” with symptom code 20859
- The customer only complained about a warning lamp lighting up.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

This bulletin replaces PSS TSB 2078847, *35 PSS Gearbox: Drive system fault in instrument cluster, DTC P071100 symptom 20756 - diagnostic address 0002*.

Combined software update

The complaint is solved with the target combined software version 03.10.00/C [KD2]. This combined software package has already been rolled out.

Please note that the KD package may have been superseded by a subsequent combined software update.

All information about the current schedule and availability of the measure can be found in central service information 2081477.

Please also note any changes in the warranty accounting instructions

Warranty

Please note the following accounting instructions:

The TSB number of this complaint-related TSB must always be stated for ease of processing. The TSB number must always be noted in the “HST number” field in SAGA/2 for ease of processing.

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	3730		
Damage Code:	KD2S		
Labor Operations:	Work for a combined software update	Please refer to central service information TSB 2081477	Please refer to central service information TSB 2081477
Claim Comment:	As per TSB 2079998/5		

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in the vehicle. Please inform the customer about the software update in question and ask whether they or other third parties have modified the software (e.g. tuning or retrofitting involving modifications to the vehicle's software). Please inform the customer that this software update may neutralize previous modifications to the vehicle's software performed either by the customer or other third parties.

If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

It is also possible to reset individual user settings for the assist systems to the default settings. These settings can be adjusted individually by the vehicle users themselves after the software update.

All part and service references provided in this TSB (**2079998**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.