Connection offline

Vehicle-specific service

Transaction No.: **2083287/1**

01 PSS Postpone repair: engine control unit - event memory entry P001400 Camshaft Position - 2.0 ltr. 4-cyl. TFSI

Release date: Sep 18, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
A5 (FU), Q5, and Q5 Sportback (GU)	2025	All	2.0 ltr. 4-cyl.			
			00A5 - Front sensor for driver assistance systems			
			Software part number	**Software version**	**Hardware part number**	**Hardware version**
			*	0295	*	*
			*	0250	*	*
			*	0381	*	*
			*	0386	*	*

Customer states:

- The exhaust emissions warning lamp lights up.

Workshop findings:

- The following entry is logged in the event memory of the engine control unit: “P001400 – B Camshaft Position (Bank1) Timing over-advanced or System Performance”

Technical Background

Software issue in engine control unit (address 0001)

Production Solution

Not applicable.

Service

Please postpone repair. A combined software update with the target combined software version 03.20.00/C [KD3.0] is currently being implemented. It will be rolled out in stages for the different models and markets. All information about the current schedule and availability of the measure can be found in the central service info 2081477, *00 Service info: central overview of combined software updates for cluster 3, PPE/PPC [03.11.00/C_03.20.00/C]*.

As a part of the process, please create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service* | *AU-US* > *Pending Service Solutions (PSS)*.

- Please delete the event memory.

The entry only occurs very sporadically under specific conditions, it is unlikely to reoccur.

Warranty

Replacing parts of attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

The TSB number must always be noted in the “HST number” field in SAGA for ease of processing.

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	GFF	0150 0010	Please bill according to the time required
	GFF	0150 0060	Labor according to the diagnostic log
Claim Comment:	As per TSB 2083287/1		

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The entry only occurs very sporadically under specific conditions, it is unlikely to reoccur

All part and service references provided in this TSB (**2083287**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.