STELLANTIS PARTS & SERVICES

Technical Service Bulletin (TSB)

Tire Pressure Monitoring System (TPMS) Red XX Displayed and/or Warning Indicator Illuminated

REFERENCE:	**TSB:** 08-377-26 **GROUP:** 08 - Electrical	**Date:**	October 15, 2026	**REVISION:**	—

VEHICLES AFFECTED:	**2026 (D2) RAM 3500 Pickup** **2026 (DJ) RAM 2500 Pickup** **2026 (DP) RAM 4500/5500 Cab Chassis** **This bulletin applies to vehicles built on June 04, 2026 (MDH 0604XX) equipped with Tire Pressure Monitoring Display (Sales code XGM).**	**MARKET APPLICABILITY:** ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH **NOTE: This bulletin applies to North America markets.**
CUSTOMER SYMPTOM:	**Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):** • C1501-31 - Tire Pressure Sensor 1-No Signal. • C1502-31 - Tire Pressure Sensor 2-No Signal. • C1503-31 - Tire Pressure Sensor 3-No Signal. • C1504-31 - Tire Pressure Sensor 4-No Signal. • C1505-31 - Tire Pressure Sensor 5-No Signal. • C1506-31 - Tire Pressure Sensor 6-No Signal. **Customers may also comment on the following:** • TPMS displaying red "XX" for one or more sensors and/or the tire pressure warning light is on in the Instrument Panel Cluster (IPC).	
CAUSE:	**Missing sensor battery tag**	

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-191, date of issue October 15, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves scanning the TPMS sensors and replacing TPM sensor(s) found in the provided table.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
22-14-01-9D	Sensor, Tire Pressure Monitoring (TPM) - Replace 1 Sensor and Program (1 - Semi Skilled)	6 - Electrical and Body Systems	0.7 Hrs.
22-14-01-9E	Sensor, Tire Pressure Monitoring (TPM) - Replace 2 Sensors and Program (VIN# SG512443 and SG507214 ONLY) (1 - Semi Skilled)	6 - Electrical and Body Systems	0.9 Hrs.
Failure Code	ZY	Service Action	

RELATED LOP(S):

Labor Operation No:	Labor Description	Skill Category	Labor Time
22-14-01-60	Sensor, Tire Pressure Monitoring (TPM) - Replace 2 Sensors and Program (VIN# SG512443 and SG507214 ONLY) (1 - Semi Skilled)	6 - Electrical and Body Systems	0.1 Hrs.

SPARE PARTS:

Qty	Part No.	Description	Notes
(AR)	68591551AB	Sensor, Tire Pressure	**Return sensors to the parts department for retention**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTC or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customers VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or equivalent	-	-

REPAIR PROCEDURE:

NOTE: Do not automatically replace any of the TPM sensors. Only replace the sensor(s) listed in the table below.

1. Is the VIN listed on the RSU VIN list?
   - YES>>> Proceed to Step 2.
   - NO>>> This bulletin does not apply.
2. Using wiTECH, scan the TPM sensor identifications.
3. Locate the VIN in Table 1: VIN And TPM Sensor ID on page 3.
4. Replace the TPM sensor(s) listed by ID in the table as required. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 22 - Tires and Wheels / Tire Pressure Monitoring / Sensor, Tire Pressure Monitoring (TPM) / Removal and Installation.
5. Clear DTCs.

Table 1: VIN And TPM Sensor ID

VIN	TPM SENSOR ID TO REPLACE	VIN	TPM SENSOR ID TO REPLACE
The following VINs will require two TPM sensors replaced:			
3C63R5CL1SG512443	550A1D6B 550A1D12	3C63RRJL2SG507214	550A1E6C 550A1F77
The following VINs will require one TPM sensor replaced:			
3C63R3AL1SG507928	550A1DA1	3C63R5FL7SG501409	550A1F05
3C63R3EL4SG506122	550A1CE0	3C63R5FL7SG505962	550A1F79
3C63R3GL1SG505300	550A1DCC	3C63R5FL7SG506111	550A1E3F
3C63R3GL1SG505488	550A1ED3	3C63R5FL8SG504433	550A1D5B
3C63R3GL7SG503972	550A1DF3	3C63R5FL8SG504948	550A1E74
3C63R3JL4SG529051	550A1EB1	3C63R5FL8SG506411	550A1E7B
3C63R3JL9SG528994	550A1F58	3C63R5FL8SG507008	550A1CF3
3C63R5CL0SG502406	550A1D50	3C63R5FL8SG508501	550A1F81
3C63R5CL1SG502933	550A1E46	3C63R5FL9SG501430	550A1D68
3C7WRKAJ6SG517114	550A1D6B	3C63R5FL9SG506837	550A1D83
3C6UR5HJ4TG253329	550A1F09	3C63R5FLXSG507057	550A1F22
3C63R5CL2SG509115	550A1DFA	3C63R5FLXTG248250	550A1C90
3C63R5CL2SG511222	550A1D7D	3C63R5HL1SG517182	550A1F37
3C63R5CL2SG512130	550A1ECD	3C63R5HL5SG513992	550A1EAD
3C63R5CL3SG508684	550A1E34	3C63R5KL1SG506191	550A1ED8
3C63R5CL4SG510041	550A1CDF	3C63R5NL5SG504262	550A1DE8
3C63R5CL4SG511707	550A1E21	3C63R5NL8SG504708	550A1D98
3C63R5CL5SG502935	550A1E6F	3C63R5SL1SG504151	550A1D61
3C63R5CL6SG501552	550A1EBA	3C63R5SL2SG508242	550A1F1D

3C63R5CL6SG512082	550A1E98	3C63R5SL3SG509075	550A1DA5
3C63R5CL7SG511944	550A1EAA	3C63R5SL5SG504119	550A1CFE
3C63R5CL7SG513967	550A1F7D	3C63R5SL6SG502797	550A1D8B
3C63R5CL9SG507765	550A1E28	3C63R5TL1SG514368	550A1F65
3C63R5CL9SG511170	550A1EC3	3C63R5TL8SG509846	550A1DDE
3C63R5CLXSG508732	550A1DA8	3C63R5TLXSG510450	550A1DF8
3C63R5DL0SG511816	550A1F31	3C63RRGL0SG505257	550A1DBF
3C63R5DL1SG508505	550A1D57	3C63RRGL1SG503632	550A1CD8
3C63R5DL2SG507847	550A1EF8	3C63RRGL2SG515529	550A1F19
3C63R5DL2SG510070	550A1E3C	3C63RRGL4SG515628	550A1D6D
3C63R5DL4SG508434	550A1CF4	3C63RRGL5SG503570	550A1E38
3C63R5DL5SG505008	550A1F60	3C63RRGL6SG503545	550A1D03
3C63R5DL5SG509107	550A1D8C	3C63RRGL7SG502064	550A1EE5
3C63R5DL5SG510922	550A1EDF	3C63RRGL7SG515011	550A1DD3
3C63R5DL5SG514873	550A1E0B	3C63RRGL9SG503362	550A1E4B
3C63R5DL6SG504787	550A1E14	3C63RRGL9SG504169	550A1DED
3C63R5DL6SG508936	550A1DC0	3C63RRGL9SG509422	550A1D94
3C63R5DL7SG502496	550A1EA0	3C63RRGLXSG509431	550A1E2B
3C63R5DL7SG508279	550A1DCA	3C63RRGLXSG509610	550A1D43
3C63R5DL7SG512154	550A1F26	3C63RRHL1SG509347	550A1D45
3C63R5DL9SG501866	550A1E6E	3C63RRHL3SG506711	550A1E89
3C63R5DL9SG503097	550A1EA3	3C63RRHL5SG502286	550A1EC8
3C63R5DL9SG510034	550A1D7E	3C63RRJL1SG503459	550A1E67
3C63R5DL9SG512527	550A1EB3	3C63RRJL1SG505261	550A1E2C
3C63R5DLXSG501973	550A1F80	3C6UR5NL8SG504891	550A1DD9
3C63R5DLXSG508695	550A1CF9	3C6UR5JL4SG511178	550A1E90
3C63R5DLXSG509135	550A1EF6	3C63RRJL5SG506638	550A1CD4
3C63R5DLXSG510964	550A1E33	3C63RRJL7SG501490	550A1D06
3C63R5EL3SG507631	550A1ED2	3C63RRJL8SG502101	550A1EC4
3C63R5EL6SG501516	550A1F32	3C63RRJL9SG501457	550A1DD6
3C63R5FL1SG501776	550A1DAF	3C63RRJL9SG505587	550A1F1C
3C63R5FL1SG501826	550A1EDB	3C63RRML4SG501491	550A1D5D
3C63R5FL1SG504306	550A1E85	3C63RRPL8SG504034	550A1DF0
3C63R5FL1SG504483	550A1F68	3C6UR5CJ6SG514286	550A1E1B
3C63R5FL1SG505245	550A1E0A	3C6UR5CJ9SG514282	550A1DB5
3C63R5FL1SG506394	550A1F75	3C6UR5CL5SG508285	550A1D79
3C63R5FL3SG506378	550A1D02	3C6UR5CL5SG511915	550A1E7D
3C63R5FL3SG514321	550A1CCF	3C6UR5CL7SG508238	550A1E02
3C63R5FL4SG516675	550A1D9D	3C6UR5CL7SG508370	550A1E72
3C63R5FL5SG501859	550A1E93	3C6UR5CL9SG508368	550A1EC7
3C63R5FL5TG256904	550A1F71	3C6UR5FL2SG513004	550A1CD9
3C63R5FL6SG511770	550A1D70	3C6UR5FL3SG509916	550A1EA2

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.