STAR ONLINE PUBLICATION

Case Number: S2625000006

Release Date: October 2026

Symptom/Vehicle Issue: EVIC Message "service DEF system see dealer" and Malfunction Indicator Lamp (MIL) Illuminated. Diagnostic Trouble Codes (DTC)s P218F, P202E, P2D1F, P2EAE

Models Affected:

2026 RAM DD 3500	2026 RAM DP 4500/5500

Repair Procedure: Remove skid plate from DEF Tank. Inspect line at Urea Delivery Module connection point. If the line is pinched, or rotated causing a restriction, remove and replace the line with the most current part available. Test drive for 15 min to confirm DTCs do not return.





This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous case details that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.