Nissan Group of the Americas
Copyright©

TECHNICAL SERVICE BULLETIN

Classification:	Reference:	Date:
DA26-003	NTB26-047	September 22, 2026

BSW WARNING WITH C1E00-47 AND/OR C1E80-47 STORED IN SIDE RADAR REAR LH AND/OR SIDE RADAR REAR RH

APPLIED VEHICLES: 2025 Murano (Z53)
APPLIED SYSTEMS: BSW (Blind Spot Warning)

IF YOU CONFIRM

The BSW warning was displayed, and one or more of the following DTCs are stored as Current:

- C1E00-47 for "Control Unit" stored in the Side radar "Rear Left"
- C1E80-47 for "Control Unit" stored in the Side radar "Rear Right"

ACTION

1. Confirm the current part number of the Side Radar (Rear LH) and/or Side Radar (Rear RH) that corresponds to the stored DTC(s).
2. Based on the DTCs stored, individually reprogram each applicable Side Radar (Rear LH) and/or Side Radar (Rear RH).

IMPORTANT: The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire **SERVICE PROCEDURE** as it contains information that is essential to successfully completing this repair.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Based on the stored DTC(s), use CONSULT 4 to confirm each applicable current Side Radar (Rear LH) and/or Side Radar (Rear RH) control unit part number and write it on the repair order.
   - If either Side Radar control unit matches the part number in **Table A**, continue to step 2 below.
   - If neither match the part number in **Table A**, this bulletin does not apply. Go back to ASIST for further diagnostic and repair information.

Table A

MODEL	CURRENT ECU PART NUMBER: 988J2-
2025 Murano	7UA1B

WARNING **CAUTION** ***NOTICE***

If you are not familiar with the CONSULT Reprogramming procedure, refer to the CONSULT Operation Manual and the Electronic Service Manual (ESM) for steps to reprogram an Electronic Control Unit (ECU). Follow all precautions in both manuals to prevent possible personal injury or death and/or damage to the ECU.

2. Reprogram the Side Radar (Rear LH) and/or Side Radar (Rear RH) control unit.

   IMPORTANT: When using CONSULT 4, follow the "Vehicle Menu" and select the **Vehicle reprogramming** option under "Tool Menu" to reprogram the ECU.

3. After erasing all DTCs, print a copy of the CONSULT screen showing the before and after part numbers of the control unit and attach it to the repair order.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Check the Current Part Number	(1)	RXN5AA	ZE	32	0.3
Check Part Number & Reprogram the Side Radar One		RXN7AA			0.4
Check Part Number & Reprogram the Side Radar Both		RXN6AA			0.5

(1) Reference the electronic parts catalog and use the Side Radar Driving Aid Controller Assy (284N0-*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 22, 2026	NTB26-047	Original bulletin published