Connection offline

Technical Service Bulletin

Transaction No.: **2078609/7**

94 Message in cluster: "Left/right main beam headlight defective. See owner's manual" DTC C12FC01

Release date: Oct 2, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
			Front sensor for driver assistance systems – 00A5			
			Software part number	**Software version**	**Hardware part number**	**Hardware version**
Q5, Q5 Sportback, SQ5, and SQ5 Sportback (GU)	2025	All	*	0295	*	*
			*	0250	*	*

REVISION HISTORY		
Revision	**Date**	**Purpose**
7	-	Revised *Service* (Updated work instructions) Revised *Warranty* (Update warranty table)
6	04/06/2026	Revised header (updated module SW filter)
5	02/19/2026	Revised *Warranty* (Update warranty table)

Customer states:

- The yellow warning message "Left/right main beam headlight defective. See owner's manual" appears in the instrument cluster while driving.
- There are no functional restrictions in the main beam headlights.
- The warning lamp disappears after switching the ignition off and then on again but subsequently appears intermittently.

Workshop findings:

- The complaint can be reproduced.
- DTC ***C12FC01 LED channel 4, electrical fault, symptom 139272*** is stored in diagnostic address 0029 (Left light control) and/or 0039 (Right light control).
- There are no functional restrictions in the main beams/additional main beams.

Technical Background

Software issue.

Production Solution

Optimized target data container (TDC) for diagnostic addresses 0029 and 0039 from week 26/2025 onwards.

0029 – 8MA.909.519.E - 0001

0029 – 8MA.909.520.E - 0001

Service

This TSB replaces PSS 2078182, *94 Warning lamp in instrument cluster: "Left/right main beam headlight defective. See owner's manual" DTC C12FC01*.

The complaint is solved with the target combined software version 03.10.00/C [KD2]. This combined software package has already been rolled out. Please note that the KD package may have been superseded by a subsequent combined software update. All information about the current schedule and availability of the measure can be found in central service information 2081477. Please also note any changes in the warranty accounting instructions.



The software update described in TPI 2081477 will be released in stages for the individual vehicle models/markets, depending on availability.

The combined software update TPI 2081477 may not be available for your vehicle or your market at the current time.

Please note that no further email notifications will occur.

It is recommended to check regularly whether new revisions of TPI 2081477 have been published for other vehicle groups.

Warranty

The TSB number must always be noted in the "HST number" field in SAGA/2 for ease of processing.

If you are billing according to the warranty guidelines, please note the following accounting instructions:

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9407		
Damage Code:	KD2S		
Labor Operations:	Please refer to central service information 2081477	Work for a combined software update	Please refer to central service information 2081477
Claim Comment:	As per TSB 2078609/7		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

When carrying out this TSB, time stamps are not required for billing under warranty. You are therefore permitted to work on other vehicles at the same time. The update can also be performed by non-productive personnel.

Additional Information

All part and service references provided in this TSB (**2078609**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.