Connection offline

Technical Service Bulletin

Transaction No.: **2079729/4**

96 Various messages relating to driver assist systems, event memory entry U110100 logged in various control units

Release date: Oct 16, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
			00C5 - Thermal management			
			Software part number	**Software version**	**Hardware part number**	**Hardware version**
A5, S5 (FU), A6 Sportback e-tron, S6 Sportback e-tron, Q5, Q5 Sportback, SQ5, SQ5 Sportback (GU), Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron	2025	All	*	2434	*	*
			*	2497	*	*

REVISION HISTORY		
Revision	**Date**	**Purpose**
4	-	Revised header (Updated control units) Revised *Service* (Updated reference) Revised *Warranty* (Updated labor operations) Revised *Additional Information* (Added software update information)
3	12/17/2025	Revised *Warranty* (Updated Labor Operations)
2	11/10/2025	Revised header (add A6/A5/Q5) Revised *Warranty* (Updated Labor Operations)

Customer states:

Various messages relating to driver assist systems.

Workshop findings:

The customer statement can be reproduced.

The entry ***"U110100: Component protection active, active/static*, *symptom: 1231633*"** is logged in one or more event memories of the short-range radars (diagnostic addresses 8109, 810A, 810B, 810C) and/or adaptive cruise control units (diagnostic addresses 0013, 008B).

Technical Background

Due to a software issue in onboard supply control unit -J519- (diagnostic address 0009), the component protection in the short-range radars is no longer deactivated.

Functional issues occur when component protection is active.

Production Solution

Production change in the fourth quarter of 2025.

Service

This TSB replaces Pending Service Solution (PSS) TSB 2078209: *91 PSS Various messages relating to driver assist systems, event memory entry U110100 logged in various control units*.

The complaint is solved with the **target combined software version 03.10.00/C [KD2]**. This combined software package has already been rolled out. Please note that the KD package may have been superseded by a subsequent combined software update. All information about the current schedule and availability of the measure can be found in **central service information 2081477**. Please also note any changes in the warranty accounting instructions.

Warranty

The TSB number must always be noted in the “HST number” field in SAGA/2 for ease of processing.

If you are billing according to the warranty guidelines, please note the following accounting instructions:

Repair operations: please refer to central service information 2081477.

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9710		
Damage Code:	KD2S		
Labor Operations:	Please refer to central service information 2081477	Work for a combined software update	Please refer to central service information 2081477
Claim Comment:	As per TSB 2079729/3		

Please note the information on predecessors and items that are included and excluded in the repair operations as well as any associated tasks.

When performing the combined software update, time stamps are not required for billing under warranty. You are therefore permitted to work on other vehicles at the same time. The combined software update can also be performed by non-productive personnel.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in the vehicle. Please inform the customer about the software update in question and ask whether they or other third parties have modified the software (e.g. tuning or retrofitting involving modifications to the vehicle’s software). Please inform the customer that this software update may neutralize previous modifications to the vehicle’s software performed either by the customer or other third parties.

If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

All part and service references provided in this TSB (**2079729**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.