



Bulletin No.: PIP6038
Published date: 01/22/2025

Preliminary Information

PIP6038 Malfunction Indicator Lamp (MIL) Illuminated on Driver Information Center (DIC) - DTC P0442 Set Current or History

Models

Brand: Model: Model Years:			VIN: from to		Engine:	Transmissions:
Buick	Envista	2025	All	All	All	All
Chevrolet	Trax	2025	All	All	All	All

Involved Region or Country	North America
Condition	Customer may comment that the malfunction indicator lamp is on. Technicians may find DTC P0442 is set as current or history.
Cause	Faulty fuel filler pipe.

Correction:

Dealers are to replace the fuel filler pipe.

Refer to SI for the replacement procedure to replace the fuel filler pipe.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4028270	Fuel Tank Filler Pipe Replacement	Use Standard Published Labor Time

Version History

Version	1
Modified	01/22/2025 - Created on.

