



Technical Service Bulletin

90 PSS Yellow Battery Warning Lamp + P0A1F00

90 25 60 2076606/1 January 15, 2025.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron GT, RS e-tron GT, Q5, Q5 e quattro, Q5 Sportback, SQ5, SQ5 Sportback, Q7, SQ7, Q8, SQ8, RS Q8, Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024	All	Not Applicable

Condition

This bulletin applies to MY24 A4, A5, A6, A7, A8, Q5, Q7, Q8, Q8 e-tron, e-tron GT vehicles only.

Customer states:

The customer complains that there is a yellow warning lamp in the instrument cluster with a message about a battery management fault (12V system).





Technical Service Bulletin

Figure 1. 12V Warning lamp and message

The warning lamp disappears after switching the ignition off and then on again but may appear again.

Workshop Findings

The following DTC is stored in the Data Bus On Board Diagnostic Interface, J533 (address word 0019):

- **P0A1F00:** Battery Energy Control Module Malfunction

Technical Background 1

Software issue with software version SW3039

Production Solution

Production change is scheduled for Q3/2025.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 1st quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9035		
Damage Code:	0039		
Labor Operations:	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
	GFF / Guided Functions	0150 0010	See SRT with associated operations
Claim Comment:	As per TSB 2076606/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2076606**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.