



Bulletin No.: PIP6022
Published date: 02/7/2025

Preliminary Information

PIP6022 Lost Communication with Center Stack Module/Low Radio/Vehicle Cockpit Unit DTC U11FD

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado EV	2025	All	All All	All
GMC	Sierra EV	2025	All	All All	All

Involved Region or Country	North America
Condition	Some technicians may notice DTC U11FD Lost Communication with Radio - Processor 2 (radio may also referred to as the center stack module/ low radio/ vehicle cockpit unit throughout SI) set as current or history in the K107. This DTC is Type C and will not set a MIL.
Cause	Older versions of K107 (Drive Motor Control Module) Software may induce this DTC intermittently.

Correction:
Update the K107 / K107B Drive Motor Control Modules

Warranty Information

Labor Operation	Description	Labor Time
* 2880037	Update K107 Drive Motor Control Modules	0.5 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	02/07/2025 Created on.