

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title		Ref. No.	
DIM Message and DTC IEM P060796		TJ 37093.2.0	
Issuer (Dept.)		Issue Date	Status Date
Technical Service		12/2/24	1/29/25
Car Market	Partner	Function Group	
United States and Canada	3 US 7510 Volvo Car USA	3233	
Function Description		Page	
Electric converter, high voltage		Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Updated VST Operation No, Vehicle Types, and Service.

If a customer experiences a "Propulsion System Service Required" message in the DIM during start-up in combination with diagnostic trouble code IEM P060796 set, please follow the advice under "Service".

DIM = Driver Information Module

IEM = Inverter Electric Rear Axle Drive

CSC Customer Symptom Codes

Code	Description
7G	Text window and warning symbol/Yellow symbol and text message
IV	Text window and warning symbol/Text message
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
IEM	P060796	Permanent
IEM	P060796	Intermittent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	EH	E400V8					2024-2025		-	202317-202447
536	ER	E400V12					2024-2025		-	202317-202447
539	EH	E400V8					2024-2025		-	202317-202447
539	ER	E400V12					2024-2025		-	202317-202447

Technical Journal 37093.2.0

SERVICE:

*A software solution is introduced with version 3.3.16. Perform a software upgrade according to TJ 31543.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
36004-2	Software Control Module downloading

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use the concern area "Vehicle Report" and the sub-concern area "Support Needed", use function group 3233.