

February 14, 2025

Version 1

MIL is on with DTC P060A**APPLIES TO**

Year	Model	Trim Level	VIN Range
2023–24	Accord	ALL	ALL

SYMPTOM

Multiple warning lights on and the vehicle may go into fail-safe mode; DTC P060A Powertrain Control Module (PCM) Internal Control Module Malfunction has set.

POSSIBLE CAUSE

Due to internal hardware failure, the PGM-FI detects DTC P060A and illuminates the MIL.

CORRECTIVE ACTION

Replace the PCM if DTC P060A is stored.

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1211K3	Replace PCM	0.6 hr	03214	08901	A25025A	37820-6NA-A68

PARTS INFORMATION

Part Name	Part Number	Quantity
Powertrain Control Module [CONT MOD, POWERTRAIN]	37820-6NA-AW1	1

REQUIRED TOOLS / MATERIALS

NONE

REPAIR PROCEDURE

1. [Remove and replace the PCM](#) if P060A DTC is stored.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.