



Service Bulletin

Bulletin No.: PIE0816A

Date: March, 2025

ENGINEERING INFORMATION

Subject: Engineering Information – Check Engine Lamp Illuminated on Driver Information Center (DIC), DTC P219A Set

This EI has been revised to end the need for gathering further information from the field. Please discard PIE0816.

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2025	2025	—	—	Equipped with 1.2L (RPO LBP, LIH)	—
	Envista						
Chevrolet	Trailblazer (VIN M)						
	Trax						

If you encounter a vehicle with the above condition, refer to the latest version of PIP5929 for further diagnosis.

Version	2
Modified	Released February 13, 2025 Revised March 05, 2025 – Ended the need for gathering further information from the field.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.