



STAR ONLINE PUBLICATION



Case Number: S2523000034

Release Date: April 2025

Symptom/Vehicle Issue: C008E-00 Setting After Windshield Replacement

Customer Complaint/Technician Observation: Service Forward Collision Warning message on cluster. Tech may find diagnostic trouble code (DTC) C008E-00 central ADAS decision module (CADM) ECU Internal Performance.

Discussion: Feedback from technicians after a windshield glass has been replaced is non-MOPAR glass could cause C008E-00 DTC to set. Inspect the glass stamping mark. If the C008E-00 is setting after glass replacement and the glass is found to be not a genuine MOPAR glass, the recommendation would be to replace it with the correct MOPAR windshield. MOPAR glass will be marked with the MOPAR or Jeep corporate logo.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.