

Audi On-car analysis list from April, 03 2025

Please contact Audi Helpline before attempting repair

	Models	MY	Engine	Trans	Topic	Topic details
	Q5	2021-2024	2.0T	Any	Cylinder head cover bolts leaking	Oil is leaking from the cylinder head cover bolts. Attach photos of leak to TAC case Contact TAC for direction
	Q5	2022-2025	2.0T	Any	Oil leak from oil filter	Clear photos showing oil leak and oil filter o-ring Contact TAC with photos attached in case
	A4, A5, Q5, Q7	2022-2025	2.0L engines only	Any	Engine oil pressure switch	MIL on with DTC • P055F00 Engine Oil Pressure Out of Range ° and/or • P055C00 Engine Oil Pressure Sensor/Switch "B" Low Contact TAC for direction
	Q7	2022-2025	any	Any	Airbag light on for DTC B12251B	Before performing work on the vehicle proceed as follows: 1. Contact TAC for further instruction.
	Q7, Q8	2024-2025	any	Any	Steering column switch dislocated	Customer states steering column switch is dislocated from the column. Contact TAC with photos attached for further direction.
	A3, S3, RS3	2022-2025	any	Any	Sunroof shade binds	PQA onsite needed Inquire if the vehicle is able to be left at dealer and an onsite inspection scheduled If so, create a TAC case and wait for instruction