

Audi On-car analysis list from April 28, 2025

Please contact Audi Helpline before attempting repair

	Models	MY	Engine	Trans	Topic	Topic details
	Q5	2024, 2025	2.0T	Any	Cylinder head cover bolts leaking	Oil is leaking from the cylinder head cover bolts. Attach photos of leak to TAC case Contact TAC for direction
	Q7	2022-2025	any	Any	Airbag light on for DTC B12251B	Before performing work on the vehicle proceed as follows: 1. Contact TAC for further instruction.
	Q7, Q8	2024-2025	any	Any	Steering column switch dislocated	Customer states steering column switch is dislocated from the column. Contact TAC with photos attached for further direction.
	A4, A5, Q5, A6, A7, Q7, Q8	2024-2025	any	Any	MIB3 takes a long time to load at startup	During initial bootup the MMI system takes a long time to load. Once loaded, the "User" tile is missing from the MMI home page. MMI will then typically load as a guest user. MMI system works normally otherwise. On site analysis needed. Contact TAC for further instruction
	A4, A5, Q5, A6, A7	2020, 2021	any	Any	Quattro Ultra binding	Additional information needed for vehicles with Quattro ultra binding. Ultra vehicle with PR code GH4 ◦ TSB 2075681 applies to the vehicle ◦ Minimum 35,000miles ◦ NO Previous work done for this concern Contact TAC for further direction
	Q8	2022-2025	any	Any	Front or rear window not closing correctly/reverses direction	The affected window doesn't close completely but reverses it's direction. In some cases, the window opens autonomously. Contact TAC for further direction
	A3, S3, RS3	2022-2025	any	Any	Sunroof shade binds	PQA onsite needed Inquire if the vehicle is able to be left at dealer and an onsite inspection scheduled If so, create a TAC case and wait for instruction