



Bulletin No.: PIT6281B
Published date: 05/5/2025

Preliminary Information

PIT6281B SES MIL With ECM DTC P00FF and BCM DTC U1962

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2025	SOP	January 8, 2025	All	All
Cadillac	Escalade ESV	2025	SOP	January 8, 2025	All	All
Chevrolet	Suburban	2025	SOP	January 8, 2025	All	All
Chevrolet	Tahoe	2025	SOP	January 8, 2025	All	All
GMC	Yukon	2025	SOP	January 8, 2025	All	All
GMC	Yukon XL	2025	SOP	January 8, 2025	All	All

Involved Region or Country	North America
Condition	A customer may experience a SES MIL and when scanning for DTCs there may be an ECM P00FF and BCM U1962 set.
Cause	The cause of this condition could be the BCM calibrations.

Correction:
Updated BCM calibrations have been released. Using TLC/SPS reprogram the BCM with the latest calibrations.

NOTE: Do not replace the Telematics Control Module or Body Control Module.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

Additional SI Keywords

U0499 U0485

Version History

Version	3
Modified	11/12/2024 - Created on. 01/09/2025 - Updated Models 05/05/2025 - Update to the Cause, Correction, Models, and Warranty sections.