



Bulletin No.: PIC6607
Published date: 05/9/2025

Preliminary Information

PIC6607 Super Cruise Unavailable Message

Models

Brand: Model: Model Years:		VIN: from to		Engine:	Transmissions:
Cadillac LYRIQ	2026	All	All	All	All
Cadillac VISTIQ	2026	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL
Condition	Super Cruise Unavailable message.
Cause	To be root caused by technician.

Correction:

If the following DTCs are setting in history, DO NOT replace the Image Processing Module.

U3000 SYM49, U1624 SYM00, U0140 SYM00, U023B SYM00, U053C SYM00, B1DD0 SYM57.

These DTCs setting in history are NOT related to the main reason why Super Cruise is unavailable and should be ignored.

Use SI Document ID 6763330 (Super Cruise Malfunction) and Customer Concern Verification sheet found in Global Connect under forms as an aid to diagnose.

Version History.

Version	1
Modified	05/09/2025- Created on.