



Service Bulletin

Bulletin No.: PIP6067

Date: May, 2025

PRELIMINARY INFORMATION

Subject: P0420 Replace Three Way Catalytic Converter with Pre and Post Oxygen Sensors

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT4	2024 - 2025		All	All	2.0 LSY	All

Involved Region or Country	North America
Condition	P0420 code set as current or history.
Cause	Engineering is trying to collect parts to determine the cause.

Correction

Replace the catalytic converter, pre and post oxygen sensors.

Please remove the three way catalytic converter with the two oxygen sensors as an assembly.

Engineering does not want the oxygen sensors removed from the catalytic converter if possible

The PI will be updated or replaced with TSB once a determination has been made.

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
Use Published Labor Operation	Warm Up Three-Way Catalytic Converter Replacement	Use Published Labor Time

Version	1
Modified	05/22/2025 Created on.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.