

Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN AS TITLED.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles

VW Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Tiguan	2021-2023	All	All	All	All
Arteon	2020-2023	All	All	All	All
GTI/ Golf R	2022-2023	All	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2067689/2	5/22/2025	98-22-01TT	Update model and model year applicability.
2067689/1	7/28/2022	98-22-01TT	Original publication.

Technical Background

NOTICE

If event entry (B2F0100) above includes a symptom number other than 1124417, this Tech Tip does not apply.

DTC	Description
B2F0100	Development Code 1

The diagnostic code B2F0100 with symptom code 1124417 in the front sensors/front camera for driver assist systems control unit -R242- (diagnostic address 00A5) does not have a technical effect on the camera-based assist systems (front travel or parking, lane keeping assist, adaptive cruise control, etc.) of the vehicle. There are no restricted assist functions or customer complaints.

Production Solution

NA.

Service

The diagnostic code B2F0100: Development Code 1 with symptom code 1124417 can be ignored.

A replacement of the front camera for driver assist systems is not necessary.

Additional Information

© 2025 Volkswagen Group of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.