

## Field campaign

|                 |                                                                                     |
|-----------------|-------------------------------------------------------------------------------------|
| Topic           | Software Update   BJB and HV ECUs   Continental GT/GTC/Flying Spur   25MY (SC25/10) |
| Market area     | Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)      |
| Brand           | Bentley                                                                             |
| Transaction No. | 2077696/3                                                                           |
| Campaign number | ED40                                                                                |
| Note            |                                                                                     |
| Type            |                                                                                     |
| US code         |                                                                                     |

## Vehicle data

### 25MY Continental GT/GTC/Flying Spur

#### Sales types

| Type | MY   | Brand | Designation | Engine code | Gearbox code | Final drive code |
|------|------|-------|-------------|-------------|--------------|------------------|
| Z23* | 2025 | E     |             | *           | *            | *                |
| Z24* | 2025 | E     |             | *           | *            | *                |
| Z32* | 2025 | E     |             | *           | *            | *                |

## Documents

| Document name                   |
|---------------------------------|
| <a href="#">master.xml</a>      |
| <a href="#">ed40vinlist.pdf</a> |

.....

## Notes



## Repair instructions

### Technical background

Software updates must be applied to update the vehicles Baseline Integration Level (BiL).

The software update corrects the following Diagnostic trouble codes (DTCs):

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

### Remedy

The instructions within the 'Work' section **must** be conducted to completion.

### Customer notification

Please ensure all applicable instructions are conducted at the nearest opportunity.

### Warranty

#### SVM Update Time

Claim type: 790 or 710

Service number: ED40

Damage code: 0066

Criteria:01

Labour Operation Code: 01 51 00 00

Time: As per ODIS log (Must not exceed 200TU)

### Parts

Not Applicable

### Parts supply

Not Applicable

### Parts despatch control

Not Applicable

## Repair instructions



## Notes

### Technical background

Software updates must be applied to update the vehicles Baseline Integration Level (BiL).

The software update corrects the following Diagnostic trouble codes (DTCs):

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

### Check

Check if the vehicle is already listed as repaired in "Repair history" (in ElsaPro).

Please also refer to the "Identification" section and check if a paint identification mark is evident in the vehicle.

If the vehicle is not shown in ElsaPro as repaired, and the identification mark is not present, please conduct the instructions within the 'Work' section to completion

### Parts

Not Applicable

## Work

### CAUTION

The Bentley ODIS-S Brand Version **MUST** be at least 2.35.2 (or higher).

### CAUTION

Before conducting the onward instructions, the operative **MUST** recheck the communication method in ODIS and ensure that DoIP is selected before proceeding. Within ODIS-S, perform the following:

- On the right hand side, select the “Admin” tile (Within ‘Operating modes’)
- Select “GFF sequence” (Within ‘General information’ section)
- Under the “Selection of Communication path” drop-down menu, select “Only permit DoIP communication”.

### CAUTION

**DO NOT, UNDER ANY CIRCUMSTANCES, ATTEMPT TO CONDUCT THE SOFTWARE UPDATE VIA THE CAN NETWORK. ONLY DoIP SHOULD BE USED WHEN PERFORMING THE SVM UPDATE.**

### CAUTION

You **MUST ONLY** use the Diagnosis Interface VAS 6154 (WiFi Diagnostic Tool) in USB OPERATION or the CABLE-CONNECTED VAS 5055 for the reprogramming (updating) of the control units.

- If neither of these units are available, the VAS 5054 (A) may be used in USB MODE.
- **DO NOT** under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units.

## Battery Charger

### CAUTION

**ONLY** Chargers that meet the approved specification on the Mandatory Equipment List (available on the Bentley Hub) **MUST** be used.

- The charger must be set to a mode where a **MINIMUM** of 90a is supplied to the battery during the process. Typically, this is known as ‘Power Supply Mode’ or ‘DIAG+ Mode’.
- A voltage of exactly 14.8v must be set and maintained throughout the process.
- Please refer to the manual to ensure that these requirements are met before beginning any SVM update

## Preparation Before Update

### WARNING


Hybrid Vehicles use a High Voltage System and therefore **MUST ONLY** be worked on by suitable personnel

### CAUTION

During the update, switch off all unnecessary consumers. For example, ventilation, seat heaters, interior illumination, exterior lights ect.

Conduct a full guided fault find of the vehicle.

If a ‘Check Installation List’ pop-up appears, select ‘close’ (see below image)



Referring to TPI 2075920, address any unknown faults **BEFORE** conducting any of the below updates.

Ensure that the correct battery charger is connected to the vehicle. – Refer to the “Battery Charger” Section above.

## Obtaining Hotfix for ODIS-S

### NOTICE

**The Bentley ODIS-S Brand Version 2.35.2 does not require Hotfix. Only loading of the local flash files.**

Visit <https://bentley.atheer.io/> and log in with the following case-sensitive account details.

- Username: bilupdate
- Password: Bentley123!

### NOTICE

**If you are already logged into your retailer account, you will need to logout first. To do this, click on your account initials (bottom left corner) and click “Sign Out”.**

After logging in, using the navigation bar on the left hand side, click on the ‘conversations’ tab



Next, click the conversation named “ED40 Campaign”.

### NOTICE

**You MUST NOT leave the conversation, remove users from the conversation, delete the conversation or alter the conversation in any way. The ONLY action you are permitted to perform is download the applicable file required for this campaign.**

In this conversation, you will find a file named “ED40\_Local\_Flash\_Files”.

Left click the file name and download the folder.

After left-clicking the files to download them, the download may take circa 5-10 minutes, do not interrupt this process. You may need to wait a short period (internet speed dependent) for the files to download.

During/before the download commences, there may be a warning about a “pop-up” being blocked which will prevent the file from downloading, ensure to select option “Allow Pop-Ups from this website” to download the file. Wording may differ depending on web browser.

Locate the download file and extract it. To do this, right click the file, click "7 zip" and then "Extract here"

After successfully downloading the file, please logout of the account.

### Downloading Flash Files for ODIS-S

From the content within the 'ED40\_Local\_Flash\_Files' download, copy the content of the folder into your root c:/temp drive on your ODIS device.

- FL\_4M0915249AN\_0201\_UPD0004T0005\_V001\_S.odx
- FL\_4M0915249AM\_0207\_ABJB7A60590M1\_V001\_S.odx
- FL\_4M0915231AH\_0204\_XHX15EV0421M6\_V001\_S.odx

### High Voltage Shutdown



#### WARNING

**De-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – "De-energising high-voltage system" to do so.**

1. After de-energisation, Refer to ElsaPro Repair Group 70 'Boot carpet – To remove and fit'. Remove the boot floor and gain access to the earth cable from the 12v battery negative and the body in white (This access will be required later in the test plan).
2. Navigate to 'Special functions' and select 'SVM – Pre 372BIL5201 Hotfix Routines', then 'Perform test'.
3. Switch to 'DoIP' when prompted.
- 4a. For Continental Flying Spur Vehicles Select '1) BMC/BJB 204/207 Update Repair' and follow the on-screen instructions.
- 4b. For Continental GT/GTC Vehicles Select '8) BMC/BJB 204/207 Update Repair' and follow the on-screen instructions.
- When the tester attempts to flash '008C - Battery regulation control module' you may receive a message informing you that the pre-conditions have not been met. Select 'done/continue'.
- On the following screen (shown below) select option 2 to attempt to flash the ECU – this should allow the '008C - Battery regulation control module' to flash successfully.



#### NOTICE

**If the flash fails, perform the below actions.**

1. Exit the test.
2. Allow the car to sleep for 5 minutes.
  - a. Turn off the ignition.
  - b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
  - c. Close all doors, windows, bonnet and boot lid.
  - d. Lock the vehicle to perform a CAN-BUS sleep (wait 5 minutes).
3. Clear DTCs from '008C - Battery regulation control module'.
  - 3a. To do this, right click on control unit 008C, click Guided Functions and then click 'Clear Fault Memory'.

4. Return to 'Special functions' and run the test plan 'SVM – Pre 372BIL5201 Hotfix Routines'.
5. Within this test plan, select option 2 and run until completion.
6. Once the test has been completed, right click on control unit 008C and select guided functions. Then, read ECU Identification and ensure that the 06D0 (Battery Junction Box) appears as a subsystem within the read identification test plan.
7. Continue to the next SVM update.

### SVM Code Input



#### WARNING

Re-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – “Re-energising high-voltage system” to do so.

1. After re-energising the High Voltage System, navigate to the “Special Functions” tab in ODIS-S.
2. Navigate to 'SVM – Code Input' and enter the SVM Code.
  - a. If the vehicle is any variant of a Continental GT or GTC, enter the SVM Code: “372ED40COM01”.
  - b. If the vehicle is any variant of a Continental Flying Spur, enter the SVM Code: “373ED40COM01”.
3. On the next screen, ensure that the SVM code displayed is correct.
4. You will be shown the communication type. **This MUST be set to “DoIP”.**
  - a. If “DoIP” is not selected, select option 3 until the communication type is set to “DoIP”.
5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – “Yes”.
  - a. From here, all control modules will be interrogated and the SVM action will take place.
6. Ensure that the diagnostic device remains connected for the duration of the update.
7. Follow all on-screen prompts until the program ends.
  - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.
8. Follow the on-screen instructions to completion.
9. If you are presented with this screen (Fig 3) at the end of the update, the update was successful. Please continue to step 11.




Fig 3

10. If you encounter any errors during the update, please raise a FULL TECHNICAL DISS query.

a. Customer Statement: "ED40 Support"

b. Workshop Findings: Give a summary of the error encountered and ensure that the latest Guided Fault Finding log is submitted online.

11. After successful completion of the update, perform the following.

- Turn off the ignition.
- Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
- Close all doors, windows, bonnet and boot lid.
- Lock the vehicle to perform a CAN-BUS sleep (wait 15 minutes).


12. After 15 minutes, unlock and open the driver's door. Turn on the ignition, re-connect the battery charger and diagnostic dongle.

13. Re-run guided fault finding and clear DTCs. If any faults are present, refer to TPI 2075920. If any other faults are present, please raise a full DISS query with a full GFF log uploaded online stating the error encountered.

## Identification

Once the applicable action has been conducted, the operative must submit a warranty claim as this will show the service campaign action as complete within Elsa Pro "Repair history".

You must also add a yellow paint mark to the underside of the Fusebox cover as per the picture below.



---

 [Repair instructions](#)  [Notes](#)

| AMERICAS          | ASIA PACIFIC      | CHINESE MAINLAND HK<br>AND MACAO |
|-------------------|-------------------|----------------------------------|
| SCBBP6ZG0SC022799 | SCBBF53S1SC022529 | SCBBF53S3SC022564                |
| SCBBP6ZG1SC022682 | SCBBF53S1SC022580 | SCBBF53SXSC023047                |
| SCBBP6ZG1SC022763 | SCBBF53S2SC022815 | SCBBG53S0SC022535                |
| SCBBP6ZG1SC022911 | SCBBF53S3SC022581 | SCBBG53S0SC022549                |
| SCBBP6ZG1SC023055 | SCBBF53S5SC022825 | SCBBG53S0SC022552                |
| SCBBP6ZG1SC023122 | SCBBF53S6SC022476 | SCBBG53S0SC022728                |
| SCBBP6ZG2SC022898 | SCBBF53S6SC022901 | SCBBG53S1SC022382                |
| SCBBP6ZG2SC023114 | SCBBJ53S6SC022556 | SCBBG53S1SC022513                |
| SCBBP6ZG4SC023020 | SCBBR53S0SC022481 | SCBBG53S1SC022642                |
| SCBBP6ZG5SC022703 | SCBBR53S0SC022920 | SCBBG53S2SC022522                |
| SCBBP6ZG6SC022726 | SCBBR53S0SC023033 | SCBBG53S2SC022584                |
| SCBBP6ZG6SC022760 | SCBBR53S1SC022425 | SCBBG53S2SC022603                |
| SCBBP6ZG6SC022855 | SCBBR53S1SC023039 | SCBBG53S2SC022651                |
| SCBBP6ZG8SC022775 | SCBBR53S2SC022952 | SCBBG53S2SC022746                |
| SCBBP6ZG8SC022873 | SCBBR53S3SC022569 | SCBBG53S2SC022942                |
| SCBBP6ZG9SC022994 | SCBBR53S3SC023091 | SCBBG53S3SC022433                |
| SCBBP6ZG9SC023014 | SCBBR53S4SC022404 | SCBBG53S3SC022576                |
| SCBBP6ZGXSC022891 | SCBBR53S4SC022693 | SCBBG53S4SC022571                |
| SCBBP6ZGXSC022907 | SCBBR53S4SC023097 | SCBBG53S4SC022599                |
| SCBBP6ZGXSC023023 | SCBBR53S5SC022394 | SCBBG53S4SC022876                |
| SCBBR6ZG0SC022540 | SCBBR53S6SC022663 | SCBBG53S5SC022613                |
| SCBBR6ZG0SC022649 | SCBBR53S6SC022811 | SCBBG53S5SC022661                |
| SCBBR6ZG0SC022697 | SCBBR53S7SC022834 | SCBBG53S5SC022708                |
| SCBBR6ZG0SC022795 | SCBBR53S9SC022740 | SCBBG53S5SC022711                |
| SCBBR6ZG0SC022831 | SCBBR53S9SC023144 | SCBBG53S5SC022742                |
| SCBBR6ZG0SC023008 | SCBCF13S1SC022494 | SCBBG53S5SC022837                |
| SCBBR6ZG1SC022384 | SCBCF13S1SC022530 | SCBBG53S6SC022412                |
| SCBBR6ZG1SC022448 | SCBCF13S1SC022544 | SCBBG53S6SC022460                |
| SCBBR6ZG1SC022479 | SCBCF13S2SC022424 | SCBBG53S6SC022474                |
| SCBBR6ZG1SC022496 | SCBCF13S7SC022614 | SCBBG53S6SC022507                |
| SCBBR6ZG1SC022594 | SCBCF13S7SC023195 | SCBBG53S6SC022636                |
| SCBBR6ZG1SC022644 | SCBCF13S8SC022461 | SCBBG53S6SC022667                |
| SCBBR6ZG1SC022806 | SCBCF13S9SC022467 | SCBBG53S7SC023004                |
| SCBBR6ZG1SC022885 | SCBCF13SXSC022378 | SCBBG53S7SC023035                |
| SCBBR6ZG1SC023017 | SCBCF13SXSC022414 | SCBBG53S7SC023164                |
| SCBBR6ZG2SC022409 | SCBCF13SXSC022610 | SCBBG53S8SC022492                |
| SCBBR6ZG2SC022524 | SCBCJ13S9SC022435 | SCBBG53S8SC022542                |
| SCBBR6ZG2SC022605 | SCBCR13S4SC022545 | SCBBG53S8SC022623                |
| SCBBR6ZG2SC022717 | SCBCR13S4SC022917 | SCBBG53S8SC022752                |
| SCBBR6ZG2SC022748 | SCBCR13S6SC022725 | SCBBG53S8SC022895                |
| SCBBR6ZG2SC022801 | SCBCR13S7SC023043 | SCBBG53S9SC022470                |
| SCBBR6ZG2SC022829 | SCBCR13S8SC022807 | SCBBG53S9SC022498                |
| SCBBR6ZG2SC022880 | SCBCR13S9SC022508 | SCBBG53S9SC022517                |

|                   |                   |                   |
|-------------------|-------------------|-------------------|
| SCBBR6ZG2SC022930 | SCBDF33S2SC022486 | SCBBG53S9SC022646 |
| SCBBR6ZG2SC023012 | SCBDF33S3SC022383 | SCBBG53SXSC022445 |
| SCBBR6ZG3SC022466 | SCBDF33S4SC022375 | SCBBG53SXSC022526 |
| SCBBR6ZG3SC022628 | SCBDF33S4SC022635 | SCBBG53SXSC022719 |
| SCBBR6ZG3SC022631 | SCBDF33S7SC022452 | SCBBG53SXSC022736 |
| SCBBR6ZG4SC022377 | SCBDF33S8SC022489 | SCBBG53SXSC022851 |
| SCBBR6ZG4SC022427 | SCBDR33S0SC023076 | SCBBG53SXSC023062 |
| SCBBR6ZG4SC022511 | SCBDR33S1SC022776 | SCBCF13SXSC022655 |
| SCBBR6ZG4SC022640 | SCBDR33S9SC022587 | SCBCG13S0SC022645 |
| SCBBR6ZG4SC022671 | SCBDR33SXSC022632 | SCBCG13S1SC022573 |
| SCBBR6ZG4SC022766 | SCBBR53S6SC022940 | SCBCG13S2SC023120 |
| SCBBR6ZG4SC022833 | SCBDR33S6SC023129 | SCBCG13S3SC022381 |
| SCBBR6ZG4SC022847 | SCBBR53S2SC023082 | SCBCG13S4SC022437 |
| SCBBR6ZG4SC022914 | SCBBR53S0SC023274 | SCBCG13S4SC022499 |
| SCBBR6ZG4SC023058 | SCBCR13S4SC023016 | SCBCG13S4SC022583 |
| SCBBR6ZG5SC022422 | SCBDF33S1SC022589 | SCBCG13S6SC023024 |
| SCBBR6ZG5SC022436 |                   | SCBCG13S7SC022397 |
| SCBBR6ZG5SC022453 |                   | SCBCG13S7SC023128 |
| SCBBR6ZG5SC022520 |                   | SCBCG13S8SC022490 |
| SCBBR6ZG5SC022551 |                   | SCBCG13S9SC022434 |
| SCBBR6ZG5SC022601 |                   | SCBCG13S9SC022840 |
| SCBBR6ZG5SC022792 |                   | SCBCG13S9SC022935 |
| SCBBR6ZG5SC022839 |                   | SCBCG13S9SC023115 |
| SCBBR6ZG5SC022842 |                   | SCBCG13SXSC022832 |
| SCBBR6ZG5SC022887 |                   | SCBDF33SXSC022512 |
| SCBBR6ZG5SC023067 |                   | SCBDG33S0SC022418 |
| SCBBR6ZG6SC022509 |                   | SCBDG33S3SC022543 |
| SCBBR6ZG6SC022574 |                   | SCBDG33S3SC022624 |
| SCBBR6ZG6SC022638 |                   | SCBBG53S0SC023118 |
| SCBBR6ZG6SC022669 |                   | SCBBG53S0SC023233 |
| SCBBR6ZG6SC022817 |                   | SCBBG53S8SC023237 |
| SCBBR6ZG7SC022440 |                   | SCBCG13S0SC023021 |
| SCBBR6ZG7SC022485 |                   | SCBCG13S6SC023234 |
| SCBBR6ZG7SC022504 |                   | SCBBG53S8SC023125 |
| SCBBR6ZG7SC022695 |                   | SCBCG13S6SC023007 |
| SCBBR6ZG8SC022379 |                   | SCBDG33SXSC023222 |
| SCBBR6ZG8SC022396 |                   | SCBBG53S0SC023149 |
| SCBBR6ZG8SC022429 |                   | SCBBG53S1SC023306 |
| SCBBR6ZG8SC022558 |                   | SCBBG53S3SC023257 |
| SCBBR6ZG8SC022723 |                   | SCBBG53S7SC023276 |
| SCBBR6ZG8SC022849 |                   | SCBBG53S9SC023053 |
| SCBBR6ZG9SC022388 |                   | SCBCG13S5SC023225 |
| SCBBR6ZG9SC022438 |                   | SCBCG13S6SC023217 |
| SCBBR6ZG9SC022455 |                   | SCBCG13S9SC023244 |
| SCBBR6ZG9SC022472 |                   | SCBCG13S1SC023318 |

SCBBR6ZG9SC022620  
SCBBR6ZG9SC022701  
SCBBR6ZG9SC022827  
SCBBR6ZG9SC022925  
SCBBR6ZGXSC022416  
SCBBR6ZGXSC022450  
SCBBR6ZGXSC022464  
SCBBR6ZGXSC022514  
SCBBR6ZGXSC022531  
SCBBR6ZGXSC022562  
SCBBR6ZGXSC022609  
SCBBR6ZGXSC022657  
SCBBR6ZGXSC022819  
SCBBR6ZGXSC022867  
SCBCP2ZG0SC022749  
SCBCP2ZG0SC022993  
SCBCP2ZG0SC023075  
SCBCP2ZG2SC023126  
SCBCP2ZG3SC022678  
SCBCP2ZG3SC022888  
SCBCP2ZG3SC023068  
SCBCP2ZG5SC022830  
SCBCP2ZG5SC022908  
SCBCP2ZG6SC022822  
SCBCP2ZG6SC023002  
SCBCP2ZG8SC022949  
SCBCP2ZG9SC022684  
SCBCP2ZG9SC022698  
SCBCP2ZG9SC023107  
SCBCP2ZG9SC023138  
SCBCP2ZGXSC023178  
SCBCR2ZG0SC022387  
SCBCR2ZG0SC022406  
SCBCR2ZG0SC022566  
SCBCR2ZG0SC022616  
SCBCR2ZG0SC022650  
SCBCR2ZG0SC022793  
SCBCR2ZG0SC022812  
SCBCR2ZG1SC022575  
SCBCR2ZG1SC022608  
SCBCR2ZG1SC022625  
SCBCR2ZG1SC022852  
SCBCR2ZG1SC022947  
SCBCR2ZG1SC022995  
SCBCR2ZG2SC022505

SCBCR2ZG2SC022519  
SCBCR2ZG2SC022553  
SCBCR2ZG2SC022570  
SCBCR2ZG3SC022402  
SCBCR2ZG3SC022495  
SCBCR2ZG3SC022593  
SCBCR2ZG4SC022408  
SCBCR2ZG4SC022523  
SCBCR2ZG4SC022568  
SCBCR2ZG4SC022733  
SCBCR2ZG5SC022689  
SCBCR2ZG5SC022739  
SCBCR2ZG5SC022854  
SCBCR2ZG6SC022376  
SCBCR2ZG6SC022538  
SCBCR2ZG6SC022541  
SCBCR2ZG6SC022619  
SCBCR2ZG6SC022877  
SCBCR2ZG6SC023141  
SCBCR2ZG7SC022533  
SCBCR2ZG7SC022550  
SCBCR2ZG7SC022659  
SCBCR2ZG7SC022709  
SCBCR2ZG7SC022774  
SCBCR2ZG7SC022953  
SCBCR2ZG7SC023147  
SCBCR2ZG8SC022458  
SCBCR2ZG8SC022475  
SCBCR2ZG8SC022637  
SCBCR2ZG8SC022816  
SCBCR2ZG8SC022928  
SCBCR2ZG9SC022484  
SCBCR2ZG9SC023022  
SCBCR2ZG9SC023084  
SCBCR2ZGXSC022641  
SCBCR2ZGXSC022767  
SCBCR2ZGXSC022798  
SCBCR2ZGXSC022879  
SCBCR2ZGXSC022932  
SCBCR2ZGXSC023109  
SCBDP4ZG0SC022802  
SCBDP4ZG0SC022945  
SCBDP4ZG1SC022677  
SCBDP4ZG1SC022758  
SCBDP4ZG3SC023071

SCBDP4ZG4SC022866  
SCBDP4ZG4SC023029  
SCBDP4ZG4SC023175  
SCBDP4ZG6SC022836  
SCBDP4ZG7SC022683  
SCBDP4ZG8SC022899  
SCBDP4ZG9SC022782  
SCBDP4ZG9SC022846  
SCBDP4ZG9SC022894  
SCBDP4ZGXSC023133  
SCBDR4ZG0SC022941  
SCBDR4ZG1SC022656  
SCBDR4ZG1SC022768  
SCBDR4ZG1SC023063  
SCBDR4ZG2SC022391  
SCBDR4ZG2SC022567  
SCBDR4ZG2SC022598  
SCBDR4ZG2SC022617  
SCBDR4ZG2SC023072  
SCBDR4ZG3SC022447  
SCBDR4ZG3SC022500  
SCBDR4ZG3SC022528  
SCBDR4ZG3SC022612  
SCBDR4ZG3SC022724  
SCBDR4ZG4SC022411  
SCBDR4ZG4SC022456  
SCBDR4ZG4SC022652  
SCBDR4ZG4SC022747  
SCBDR4ZG4SC022893  
SCBDR4ZG4SC022926  
SCBDR4ZG5SC022126  
SCBDR4ZG5SC022403  
SCBDR4ZG5SC022482  
SCBDR4ZG5SC022532  
SCBDR4ZG5SC022577  
SCBDR4ZG5SC022627  
SCBDR4ZG5SC022658  
SCBDR4ZG6SC022426  
SCBDR4ZG6SC022765  
SCBDR4ZG7SC022385  
SCBDR4ZG7SC022502  
SCBDR4ZG7SC022600  
SCBDR4ZG7SC022662  
SCBDR4ZG8SC022668  
SCBDR4ZG8SC023108

SCBDR4ZG9SC022579  
SCBDR4ZG9SC022999  
SCBDR4ZGXSC022459  
SCBDR4ZGXSC022462  
SCBDR4ZGXSC022929  
SCBBP6ZG8SC022680  
SCBBR6ZG6SC023191  
SCBDR4ZG3SC023100  
SCBBP6ZG8SC023179  
SCBBR6ZG3SC023228  
SCBBR6ZG4SC023030  
SCBCP2ZG3SC022745  
SCBCR2ZG9SC023229  
SCBDP4ZG1SC023215  
SCBDP4ZG6SC022738  
SCBDP4ZGXSC022449  
SCBDR4ZG4SC023185  
SCBDR4ZG8SC023187  
SCBDR4ZGXSC023143  
SCBBP6ZG2SC023243  
SCBBR6ZG6SC023224  
SCBCP2ZG6SC023260  
SCBCP2ZG7SC023221  
SCBCR2ZG4SC023123  
SCBCR2ZG8SC023268  
SCBCR2ZGXSC022753  
SCBDP4ZG6SC023212  
SCBBP6ZG5SC022734  
SCBBP6ZG7SC022699  
SCBBP6ZGXSC023264  
SCBBR6ZG0SC023106  
SCBBR6ZG0SC023283  
SCBBR6ZG1SC022997  
SCBBR6ZG7SC023281  
SCBBR6ZG7SC023295  
SCBCP2ZG1SC023263  
SCBCP2ZG3SC023247  
SCBDR4ZG0SC023250  
SCBDR4ZG6SC023267  
SCBBP6ZG6SC023312  
SCBBR6ZG1SC023261  
SCBBR6ZG9SC023301  
SCBCR2ZG2SC023296

| EUROPE            | INTERNAL          | MIDDLE EAST AFRICA &<br>INDIA |
|-------------------|-------------------|-------------------------------|
| SCBBF53S0SC022537 | SCBBL53S8SC022875 | SCBBF53S4SC023111             |
| SCBBF53S0SC022554 | SCBCL13S1SC023038 | SCBBF53SXSC022626             |
| SCBBF53S0SC022909 |                   | SCBBF5ZG0SC022685             |
| SCBBF53S1SC022420 |                   | SCBBF5ZG2SC022560             |
| SCBBF53S1SC022918 |                   | SCBBF5ZG2SC022588             |
| SCBBF53S2SC022653 |                   | SCBBF5ZG2SC022607             |
| SCBBF53S3SC022547 |                   | SCBBF5ZG2SC023093             |
| SCBBF53S3SC022757 |                   | SCBBF5ZG4SC022611             |
| SCBBF53S4SC022590 |                   | SCBBF5ZG5SC022407             |
| SCBBF53S5SC022386 |                   | SCBBF5ZG7SC022862             |
| SCBBF53S5SC022730 |                   | SCBBF5ZG9SC022457             |
| SCBBF53S5SC022789 |                   | SCBBF5ZG9SC022488             |
| SCBBF53S7SC022860 |                   | SCBBF5ZGXSC022483             |
| SCBBF53S8SC022690 |                   | SCBBF5ZGXSC022936             |
| SCBBF53S9SC022715 |                   | SCBCF13S9SC022954             |
| SCBBF53S9SC022777 |                   | SCBCF13SXSC022803             |
| SCBBJ53S0SC022732 |                   | SCBCF1ZG0SC022442             |
| SCBBJ53S6SC023027 |                   | SCBCF1ZG0SC023168             |
| SCBBL53S2SC022676 |                   | SCBCF1ZG1SC022871             |
| SCBBL53S4SC022744 |                   | SCBCF1ZG1SC023146             |
| SCBBL53S4SC022808 |                   | SCBCF1ZG2SC023088             |
| SCBBL53S5SC022431 |                   | SCBCF1ZG3SC023083             |
| SCBBL53S7SC022821 |                   | SCBCF1ZG6SC022770             |
| SCBBL53S8SC022844 |                   | SCBCF1ZG7SC022602             |
| SCBBL53S8SC022858 |                   | SCBCF1ZG9SC022634             |
| SCBBL53S9SC022674 |                   | SCBCF1ZG9SC022665             |
| SCBBL53S9SC022786 |                   | SCBCH13S0SC022772             |
| SCBBL53S9SC023162 |                   | SCBCH13S4SC022712             |
| SCBBL53SXSC022781 |                   | SCBCJ13S0SC022923             |
| SCBCF13S0SC022454 |                   | SCBCJ13S2SC022390             |
| SCBCF13S0SC022471 |                   | SCBCJ13S6SC022506             |
| SCBCF13S0SC022521 |                   | SCBDF3ZG3SC022595             |
| SCBCF13S0SC022597 |                   | SCBDF3ZG8SC022415             |
| SCBCF13S0SC022633 |                   | SCBDF3ZG8SC022639             |
| SCBCF13S0SC022700 |                   | SCBDJ33S8SC022491             |
| SCBCF13S0SC022759 |                   | SCBDJ3ZG9SC022518             |
| SCBCF13S0SC022809 |                   | SCBCF1ZG4SC023190             |
| SCBCF13S0SC022826 |                   | SCBBF5ZG5SC023248             |
| SCBCF13S0SC022857 |                   |                               |
| SCBCF13S0SC023099 |                   |                               |
| SCBCF13S1SC022463 |                   |                               |
| SCBCF13S1SC022477 |                   |                               |
| SCBCF13S1SC022480 |                   |                               |

SCBCF13S1SC022527  
SCBCF13S1SC022673  
SCBCF13S1SC022785  
SCBCF13S1SC022897  
SCBCF13S1SC023127  
SCBCF13S1SC023158  
SCBCF13S2SC022536  
SCBCF13S2SC022780  
SCBCF13S2SC022889  
SCBCF13S2SC022892  
SCBCF13S2SC022939  
SCBCF13S2SC023086  
SCBCF13S3SC022660  
SCBCF13S3SC022741  
SCBCF13S3SC022769  
SCBCF13S3SC022903  
SCBCF13S3SC023050  
SCBCF13S3SC023064  
SCBCF13S4SC022439  
SCBCF13S4SC022604  
SCBCF13S4SC022666  
SCBCF13S4SC022778  
SCBCF13S4SC022828  
SCBCF13S5SC022417  
SCBCF13S5SC022451  
SCBCF13S5SC022465  
SCBCF13S5SC022501  
SCBCF13S5SC022823  
SCBCF13S5SC023003  
SCBCF13S5SC023096  
SCBCF13S6SC022393  
SCBCF13S6SC022510  
SCBCF13S6SC022586  
SCBCF13S6SC022622  
SCBCF13S6SC022670  
SCBCF13S6SC022720  
SCBCF13S6SC022796  
SCBCF13S6SC022913  
SCBCF13S6SC023009  
SCBCF13S6SC023057  
SCBCF13S7SC022421  
SCBCF13S7SC022578  
SCBCF13S7SC022743  
SCBCF13S7SC022869  
SCBCF13S8SC022380

SCBCF13S8SC022654  
SCBCF13S8SC022718  
SCBCF13S8SC022783  
SCBCF13S8SC022881  
SCBCF13S8SC023061  
SCBCF13S9SC022405  
SCBCF13S9SC022419  
SCBCF13S9SC022565  
SCBCF13S9SC022596  
SCBCF13S9SC022629  
SCBCF13S9SC022937  
SCBCF13S9SC023019  
SCBCF13S9SC023036  
SCBCF13S9SC023117  
SCBCF13SXSC022557  
SCBCF13SXSC022591  
SCBCF13SXSC022722  
SCBCF13SXSC022865  
SCBCF13SXSC023000  
SCBCJ13S0SC023134  
SCBCJ13S1SC022672  
SCBCJ13S6SC023025  
SCBCJ13SXSC022413  
SCBCL13S0SC022687  
SCBCL13S0SC022818  
SCBCL13S0SC023077  
SCBCL13S1SC022729  
SCBCL13S1SC022794  
SCBCL13S1SC023069  
SCBCL13S2SC022691  
SCBCL13S2SC022710  
SCBCL13S2SC022884  
SCBCL13S2SC022996  
SCBCL13S2SC023081  
SCBCL13S2SC023131  
SCBCL13S3SC022702  
SCBCL13S3SC022845  
SCBCL13S3SC022859  
SCBCL13S4SC022790  
SCBCL13S4SC022921  
SCBCL13S4SC023101  
SCBCL13S6SC022886  
SCBCL13S6SC022919  
SCBCL13S6SC023049  
SCBCL13S7SC022735

SCBCL13S7SC022931  
SCBCL13S7SC023092  
SCBCL13S8SC022713  
SCBCL13S8SC022761  
SCBCL13S9SC023112  
SCBCL13S9SC023157  
SCBCL13SXSC022874  
SCBCL13SXSC022938  
SCBCL13SXSC023037  
SCBCL13SXSC023054  
SCBCL13SXSC023166  
SCBDF33S0SC022423  
SCBDF33S0SC022731  
SCBDF33S0SC022762  
SCBDF33S1SC022592  
SCBDF33S1SC022902  
SCBDF33S1SC023015  
SCBDF33S2SC022441  
SCBDF33S2SC022469  
SCBDF33S2SC022696  
SCBDF33S2SC023105  
SCBDF33S3SC022478  
SCBDF33S3SC022559  
SCBDF33S3SC022643  
SCBDF33S3SC022755  
SCBDF33S3SC022805  
SCBDF33S3SC022870  
SCBDF33S3SC022948  
SCBDF33S4SC022389  
SCBDF33S4SC022473  
SCBDF33S4SC023087  
SCBDF33S4SC023137  
SCBDF33S5SC022630  
SCBDF33S5SC022773  
SCBDF33S5SC023034  
SCBDF33S5SC023048  
SCBDF33S6SC022555  
SCBDF33S6SC023060  
SCBDF33S7SC022497  
SCBDF33S7SC022516  
SCBDF33S7SC022841  
SCBDF33S7SC022905  
SCBDF33S8SC022525  
SCBDF33S8SC022539  
SCBDF33S8SC022606

SCBDF33S8SC022797  
SCBDF33S8SC022864  
SCBDF33S9SC022534  
SCBDF33S9SC022582  
SCBDF33SXSC022395  
SCBDF33SXSC022428  
SCBDF33SXSC022686  
SCBDF33SXSC022784  
SCBDF33SXSC023031  
SCBDL33S0SC022771  
SCBDL33S0SC022916  
SCBDL33S0SC023113  
SCBDL33S2SC022934  
SCBDL33S3SC022814  
SCBDL33S4SC022675  
SCBDL33S4SC023051  
SCBDL33S5SC022779  
SCBDL33S5SC023110  
SCBDL33S6SC022788  
SCBDL33S9SC022820  
SCBCL13S0SC023032  
SCBBF53S5SC022615  
SCBCF13S0SC023202  
SCBCF13S5SC023194  
SCBCF13S8SC023206  
SCBCL13S1SC023198  
SCBCL13S3SC022912  
SCBCL13S4SC023177  
SCBCL13S9SC023188  
SCBDF33S0SC022261  
SCBDF33S6SC023155  
SCBDF33S8SC023089  
SCBDF33S8SC023139  
SCBDF33S9SC023005  
SCBDF33S9SC023098  
SCBDL33S6SC023116  
SCBDL33S6SC023200  
SCBDL33SXSC023183  
SCBBF53S3SC023231  
SCBBL53S6SC022955  
SCBCF13S2SC023184  
SCBCF13S4SC023249  
SCBCF13S6SC022992  
SCBCF13S8SC023223  
SCBCF13S9SC023151

SCBCF13SXSC023174  
SCBCF13SXSC023241  
SCBCL13S0SC023189  
SCBCL13S4SC023213  
SCBCL13S5SC023236  
SCBCL13S7SC023240  
SCBDF33S5SC023230  
SCBDL33S0SC023242  
SCBDL33S6SC023150  
SCBBF53SXSC022853  
SCBBF53SXSC023226  
SCBCF13S1SC023211  
SCBCF13S7SC023259  
SCBBF53S6SC023286  
SCBBL53S3SC023142  
SCBBL53S5SC023255  
SCBBL53S6SC023135  
SCBCF13S1SC023273  
SCBCF13S8SC022878  
SCBCL13S8SC023196  
SCBCL13S9SC023269  
SCBDF33S1SC023256  
SCBDF33S6SC023253  
SCBDF33S6SC023284  
SCBDF33S8SC023173  
SCBDF33S9SC023313  
SCBDL33S0SC023287  
SCBDL33S4SC023258  
SCBBF53S5SC023280  
SCBCF13S6SC023026  
SCBCL13S7SC023304  
SCBDF33S4SC023297

UNITED KINGDOM

SCBBF53S0SC022392  
SCBBF53S0SC022618  
SCBBF53S7SC022664  
SCBBF53S9SC023041  
SCBBL53S1SC022927  
SCBBL53S3SC022721  
SCBBL53S5SC022882  
SCBBL53S7SC022804  
SCBBL53S7SC022933  
SCBBL53S7SC023001  
SCBBL53S9SC022688

SCBBL53SXSC022750  
SCBCF13S0SC022468  
SCBCF13S0SC022843  
SCBCF13S1SC022561  
SCBCF13S2SC022410  
SCBCF13S2SC022648  
SCBCF13S4SC022487  
SCBCF13S5SC022515  
SCBCF13S5SC023132  
SCBCF13S6SC022443  
SCBCF13S6SC022863  
SCBCF13S6SC022944  
SCBCF13S9SC022503  
SCBCF13S9SC022548  
SCBCF13S9SC022694  
SCBCF13SXSC023028  
SCBCL13S0SC022446  
SCBCL13S0SC022737  
SCBCL13S0SC022835  
SCBCL13S0SC022883  
SCBCL13S0SC022950  
SCBCL13S0SC023046  
SCBCL13S1SC022813  
SCBCL13S1SC022861  
SCBCL13S1SC023119  
SCBCL13S1SC023136  
SCBCL13S2SC023145  
SCBCL13S3SC022764  
SCBCL13S3SC023056  
SCBCL13S3SC023090  
SCBCL13S4SC022756  
SCBCL13S4SC022787  
SCBCL13S4SC023065  
SCBCL13S4SC023163  
SCBCL13S6SC022838  
SCBCL13S6SC022998  
SCBCL13S6SC023018  
SCBCL13S7SC022850  
SCBCL13S7SC022900  
SCBCL13S7SC023013  
SCBCL13S7SC023044  
SCBCL13S8SC022727  
SCBCL13S8SC022890  
SCBCL13S8SC022906  
SCBCL13S8SC023103

SCBCL13S9SC023059  
SCBCL13SXSC022681  
SCBCL13SXSC022924  
SCBCL13SXSC023006  
SCBCL13SXSC023152  
SCBDF33S0SC022647  
SCBDF33S0SC022714  
SCBDF33S0SC023040  
SCBDF33S1SC022432  
SCBDF33S4SC022585  
SCBDF33S5SC022546  
SCBDF33S5SC022563  
SCBDF33S6SC022572  
SCBDF33SXSC022493  
SCBDL33S1SC022679  
SCBDL33S2SC022951  
SCBDL33S2SC023095  
SCBDL33S3SC022716  
SCBDL33S4SC022868  
SCBDL33S5SC022751  
SCBDL33S5SC023074  
SCBDL33S5SC023124  
SCBDL33S6SC022791  
SCBDL33S6SC022810  
SCBDL33S6SC022824  
SCBDL33S6SC022872  
SCBDL33SXSC022910  
SCBBF53S0SC023171  
SCBCL13S0SC023192  
SCBCL13S1SC023170  
SCBCL13S1SC023203  
SCBCL13S6SC023066  
SCBCL13S9SC023207  
SCBDF33S7SC023181  
SCBDL33S1SC023167  
SCBDL33S9SC022896  
SCBBL53S9SC023193  
SCBCF13S6SC023172  
SCBCL13S1SC023251  
SCBCL13S3SC023154  
SCBCL13S7SC023254  
SCBCL13S8SC023201  
SCBDL33S4SC023227  
SCBBL53S7SC023239  
SCBCF13S7SC023245

SCBCL13S5SC023219  
SCBBF53S6SC023160  
SCBBL53S2SC023293  
SCBBL53S6SC023216  
SCBCF13S2SC023279  
SCBCL13S4SC023342