



**Global Telematics Box Module Over The Air Update from
5.39.1 to 5.65 TBM2.0 Software Version (FOTA)**

6/10/2025

**VEHICLES
AFFECTED:**

2023 - 2025 (JL) Jeep Wrangler
2023 - 2025 (JT) Jeep Gladiator
**This bulletin applies to vehicles equipped with a Global Telematics
Box Module (TBM) (Sales Code RDG)**

MARKET APPLICABILITY:

☒ NA	☐ MEA
☐ SA	☐ IAP
☐ EE	☐ CH

**CUSTOMER
SYMPTOM:**

Customers may experience one or more of the following:

- Error display of "Uconnect Box Requires Service/Wifi Unavailable" pop-ups; [TBM DTC B22A9-96 Internal Performance Failure].
- Error display of "Uconnect Box Requires Service" pop-ups; [TBM DTCs B1560, B1561, B1562 - Antenna loose connection].