

TECHNICAL SERVICE BULLETIN

Incorrectly Illuminated MIL With DTC P0420

25-2269

12 June 2025

Model:

Ford 2023-2024 Maverick	Engine: 2.0L EcoBoost
----------------------------	-----------------------

Markets: North American markets only

Issue: Some of the vehicles listed in the Model statement above may exhibit an incorrectly illuminated MIL with DTC P0420 stored in the PCM. This may be due to the software in the PCM.

Action: For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to reprogram the PCM.

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2023-2024 Maverick 2.0L - Reprogram Powertrain Control Module (PCM) Software Update Application In The Ford Diagnosis And Repair System (FDRS) Scan Tool. (Do Not Use With Any Labor Operation Outside Of This Article)	252269A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	RECALEM
Condition Code:	04

Service Procedure

1. Download and run the "PCM-Powertrain Control Module (PCM) Software Update" application in the FDRS scan tool.

© 2025 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.