



Service Bulletin

Bulletin No.: PIP6069

Date: June, 2025

PRELIMINARY INFORMATION

Subject: 10L80 MHO MHS MQC DTC's P1787 P27EC P187E P18A1

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2024		ALL	ALL	MHS MQC	ALL
Chevrolet	Suburban	2024		ALL	ALL	MHS MQC	ALL
Chevrolet	Tahoe	2024		ALL	ALL	MHS MQC	ALL
GMC	Sierra 1500	2024		ALL	ALL	MHS MQC	ALL
GMC	Yukon	2024		ALL	ALL	MHS MQC	ALL
GMC	Yukon XL	2024		ALL	ALL	MHS MQC	ALL

Involved Region or Country	North America Asean Asia/Pacific China Europe E Europe International Fleet Sales Israel Mid-East South America
Condition	SES MIL with any or all DTCs P1787, P27EC, P187E, P18A1 present.
Cause	Internal valve body.

Correction

If you encounter any of the above DTC's do not replace the TCM. Replace the Control Valve Body due to an internal concern. This PI will be deleted or updated into a TSB after further research.

Version	1
Modified	06/11/2025 — Created.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.