



Service Bulletin

Bulletin No.: PIP5929C

Date: March, 2025

PRELIMINARY INFORMATION

Subject: Diagnostic Tip for DTC P219A Setting with No Other Drivability Symptoms

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020-2025		All	All	1.2L LIH and LBP	All
Buick	Envista	2024-2025		All	All	1.2 LIH and LBP	
Chevrolet	Trailblazer	2021-2025		All	All	1.2L LIH and LBP	All
Chevrolet	Trax	2024-2025		All	All	1.2L LIH and LBP	All

Involved Region or Country	North America
Condition	MIL on with P219A stored in history.
Cause	Potential fuel injector issue.

Correction

If you encounter DTC P219A set in history and this is first failure occurrence please clear the code using GDS and evaluate to see if the DTC will return.

If the DTC P219A returns replace the three fuel injectors and evaluate the condition.

Version	4
Modified	06/16/2023 - Created. 12/16/2024 Updated Models and RPO code. 01/17/2025- Updated Models and RPO code. 03/07/2025 – Updated Models.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.