



# Service Bulletin

Bulletin No.: PIT6450

Date: November, 2025

## PRELIMINARY INFORMATION

**Subject: Service Brake System Message DTC C0597**

| Brand:    | Model:         | Model Year: |    | VIN: |     | Engine: | Transmission: |
|-----------|----------------|-------------|----|------|-----|---------|---------------|
|           |                | from        | to | from | to  |         |               |
| Cadillac  | Escalade       | 2026        |    | All  | All | All     | All           |
| Cadillac  | Escalade ESV   | 2026        |    | All  | All | All     | All           |
| Chevrolet | Silverado 1500 | 2026        |    | All  | All | All     | All           |
| Chevrolet | Suburban       | 2026        |    | All  | All | All     | All           |
| Chevrolet | Tahoe          | 2026        |    | All  | All | All     | All           |
| GMC       | Sierra 1500    | 2026        |    | All  | All | All     | All           |
| GMC       | Yukon          | 2026        |    | All  | All | All     | All           |
| GMC       | Yukon XL       | 2026        |    | All  | All | All     | All           |

|                                   |                                                                                                                                                                                   |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Involved Region or Country</b> | North America                                                                                                                                                                     |
| <b>Condition</b>                  | During Pre Delivery Inspection (PDI) a "Service Brake System" DIC message maybe displayed. When checking for DTCs a C0597 will be set current in the Brake System Control Module. |
| <b>Cause</b>                      | The cause of this condition could be an internal failure with the Brake Master Cylinder.                                                                                          |

### Correction

Replace the A104 Brake Master Cylinder.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description                                                                                      | Labor Time         |
|-----------------|--------------------------------------------------------------------------------------------------|--------------------|
| 2441400         | Brake Master Cylinder Replacement - With Power Brake Booster and Electronic Brake Control Module | Use Published Time |

|                 |                       |
|-----------------|-----------------------|
| <b>Version</b>  | 1                     |
| <b>Modified</b> | 11/05/2025 Created on |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.