



Service Bulletin

Bulletin No.: PIT6450A

Date: November, 2025

PRELIMINARY INFORMATION

Subject: Service Brake System Message DTC C0597 C055F

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2026		All	All	All	All
Cadillac	Escalade ESV	2026		All	All	All	All
Chevrolet	Silverado 1500	2026		All	All	All	All
Chevrolet	Suburban	2026		All	All	All	All
Chevrolet	Tahoe	2026		All	All	All	All
GMC	Sierra 1500	2026		All	All	All	All
GMC	Yukon	2026		All	All	All	All
GMC	Yukon XL	2026		All	All	All	All

Involved Region or Country	North America
Condition	During Pre Delivery Inspection (PDI) a “Service Brake System” DIC message maybe displayed. When checking for DTCs the following current DTC will be set in the Brake System Control Module: 2026 Silverado/Sierra 1500: DTC C055F 2026 Escalade/Yukon/Yukon XL/ Suburban/Tahoe: DTC C0597
Cause	The cause of this condition could be an internal failure with the Brake Master Cylinder.

Correction

Replace the A104 Brake Master Cylinder.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2441400	Brake Master Cylinder Replacement - With Power Brake Booster and Electronic Brake Control Module	Use Published Time

Version	2
Modified	11/05/2025 Created on 11/13/2025 Update to the title and condition

