



STAR ONLINE PUBLICATION



Case Number: S2521000007

Release Date: December 2025

Symptom/Vehicle Issue: P0607 stored in the ESM (Electronic Shifter Module)

Diagnosis: Voltage transients may have caused a stored DTC P0607 due to a known concern within the software

Repair Procedure: If the DTC P0607 is stored, please clear the DTC for now and do not replace any parts. If the code is active and you're unable to drive the vehicle, then replace the ESM. A software update for the ESM is planned for Q1 to address the code setting as stored

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.