



Subject: CHECK ENGINE LIGHT ON WITH DTC P0126:00	Service Alert No.: SA-062/25
	Last Issued : 12/19/2025

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2026 CX-30 (Mexico built)
2026 Mazda3 with VINS starting with JM1 (Japan built)

DESCRIPTION

Some vehicles equipped with a countermeasure Coolant Control Valve (plug in place of the thermostat inside the CCV) may experience a DTC P0126:00.
Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.
2. Perform diagnosis for DTC P0126:00 according to the instructions on MGSS:
 - CX-30 : P0126:00 [PCM (SKYACTIV-G)]
 - CX-30 : P0126:00 [PCM (SKYACTIV-G 2.5T)]
 - Mazda3: P0126:00 [PCM (SKYACTIV-G)]
 - Mazda3: P0126:00 [PCM (SKYACTIV-G 2.5T)]

NOTE: If the Workshop Manual does not identify a concern with ECT1, or any other vehicle system, advise the customer that this concern is currently under investigation with Mazda.

3. Clear the DTC and release the vehicle back to the customer.
- NOTE:** The DTC may return. If the check engine light returns with DTC P0126:00, refer to MGSS for any updated information.

PARTS INFORMATION

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

NOTE:

- **DO NOT** replace the CCV (Coolant Control Valve).
- Mazda has confirmed that the CCV is not at fault and will not repair DTC P0126:00.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.