



STAR ONLINE PUBLICATION




Case Number: S2208000054 Rev. A

Release Date: July 2022

Symptom/Vehicle Issue: Left Headlight, Park Lamp Flickers Or Is Inoperative. B162A, B163A, B1632, B16CF

Discussion: The customer may bring the vehicle in for a flickering and/or inoperative left headlight and park lamp. Upon scanning the vehicle you may one or more of the following DTC's B162A, B163A, B1632, B16CF. This may be caused by a loose G905A ground.

Diagnosis: Inspect the G905A ground located behind the left headlight housing. Confirm that the ground is tight and secure.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION



Repair Procedure: Resecure the ground and confirm the left headlight and park lamps operate normally. If the concern is still present, follow the DTC flow charts to root cause the concern.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found