



SSM 53100 2025 Explorer Active/Police Interceptor Utility - Various Speaker DTCs Stored In The ACM - Software Update

Some 2025 Explorer Active/Police Interceptor Utility vehicles may exhibit diagnostic trouble codes (DTCs) B1A01:01, B1A02:01, B1A03:01, B1A04:01, B1A05:01 and/or B1A06:01 in the audio control module (ACM). This may be due to a software concern within the ACM. To correct this condition, reprogram the ACM to the latest software level using the Ford Diagnosis and Repair System (FDRS) scan tool. For claiming, use causal part 18806 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.