



Connection offline

Vehicle-specific service

Topic	37 PSS Gearbox warning lamp, drive system fault with DTC P060A00
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2079003/1
Level	EH
Status	Released for publishing
Release date	Aug 18, 2025

Vehicle data

MY 2025 B10

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
FU*	2025	A		*	*	*
GU*	2025	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
*	*	*	*	*	*	000001	999999		

Documents

Document name
master.xml



Connection offline

Vehicle-specific service

Transaction No.: **2079003/1**

37 PSS Gearbox warning lamp, drive system fault with DTC P060A00

Release date: Aug 18, 2025

Condition

Customer States:

- The gearbox warning lamp lights up in the cluster.

and/or

- There is no customer complaint; the DTC specified in workshop findings is found in the automatic transmission control unit J217 in connection with a different complaint.

Workshop Findings:

The following DTC (static/intermittent) is logged in the transmission control unit, J217 (address word 0002):

- **P060A00** – Control module internal processor monitoring malfunction (symptom 20899).

and/or

The following DTC (static/intermittent) is logged in the main control unit for drive and suspension, J1312 (address word 812C):

- **P1FD700** – Transmission control module warning light request active (symptom 385025).

Technical Background

Not applicable.

Production Solution

Not applicable.

Service



NOTICE

This PSS may apply to vehicles still within the new model launch repair authorization period!

- **For vehicles still in the launch phase, the workshop must create a web ticket with the Technical Assistance Center (TAC) per the repair authorization, in addition to entering vehicle into PSS. Reference this TSB in the first line of the TAC case.**

Please postpone the repair as there is currently no effective repair for the complaint described by the customer.

- Please erase the event memory entry in the transmission control unit.
1. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2025 (subject to change) and that no repairs are necessary at this point.
 2. Do not replace any components for this condition since this will not resolve the customer's concern.

3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	3730		
Damage Code:	0039		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2063088/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2063088**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.