



Global Telematics Box Module Over The Air Update from
R5C1 and R5O1 to R5T TBM2.H Software Version (FOTA)

9/9/2025

VEHICLES AFFECTED:	2024-2026 (WS) Grand Wagoneer/Wagoneer 2024-2026 (WL) Grand Cherokee/Grand Cherokee L	MARKET APPLICABILITY: ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: - Error display of "Uconnect Box Requires Service/Wifi Unavailable" pop-ups; [TBM DTC B22A9-96 Internal Performance Failure]. - Error display of "Uconnect Box Requires Service" pop-ups; [TBM DTCs B1560, B1561, B1562 - Antenna loose connection]. - TBM sleep mode not working causing battery drain in some cases.	