



Global Telematics Box Module Over The Air Update from R5M1 & R5R1 to R5T TBM2.H Software Version (FOTA)

9/9/2025

VEHICLES AFFECTED:	2024 - 2026 (KM) Wagoneer S	MARKET APPLICABILITY: ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: - Error display of "Uconnect Box Requires Service/Wifi Unavailable" pop-ups; [TBM DTC B22A9-96 Internal Performance Failure]. - Error display of "Uconnect Box Requires Service" pop-ups; [TBM DTCs B1560, B1561, B1562 - Antenna loose connection]. - TBM sleep mode not working causing battery drain in some cases. - Fuel level missing in the Phone app (IOS and Android). - Incorrect "Low level fuel" pop-up message displayed in vehicle info tab when vehicle range is 100miles or more.	