



SSM 54764 2021 F-150 - Erroneous Diagnostic Trouble Code (DTC) U2404:92 Setting In the Gateway Module (GWM) After GWM Software Update

Some 2021 F-150 vehicles may exhibit an erroneous diagnostic trouble code (DTC) U2404:92 stored in the gateway module (GWM) after an over the air (OTA) update was performed or the GWM software was updated using the Ford Diagnosis And Repair System (FDRS). This may be due to various software parameters within the GWM. If this DTC is identified during normal diagnostics, but the vehicle does not exhibit any customer concerns around the GWM operation, this DTC should be disregarded. This DTC does not cause any observable concerns or warning messages and does not affect vehicle performance or durability.