

Technical Service Bulletin (TSB)

Body Control Module (BCM) Upcoming Software Update

REFERENCE:	TSB: 08-175-26 GROUP: 08 - Electrical	Date:	April 23, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (LB) Dodge Charger			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America markets.	
CUSTOMER SYMPTOM:	Technicians may find that the following Diagnostic Trouble Code (DTC) has been set: U113E-00 - Lost Communication With Intelligent Battery Sensor "A". (Active status)				
CAUSE:	BCM software				

DISCUSSION:

This Information Only bulletin provides information if DTC U113E-00 is set active. If only the BCM is actively setting the U113E-00 DTC, **do not replace the Intelligent Battery Sensor (IBS)**. A hard reset with the wiTECH needs to be performed to allow the DTC to go to stored.

NOTE: An upcoming software update will be available in the 2nd quarter of 2026 for this concern.

POLICY:

Information Only.