

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: HYBRID SYSTEM FAILURE DISPLAYED ON METER WITH DTC P2530:12	Bulletin No.: 30-001/26
	Last Issued : 04/09/2026

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previous TSBs:	Date(s) Issued:
30-001/26	02/19/26 and 03/24/26
30-001/25	06/30/25 and 05/15/25

APPLICABLE MODEL(S)/VINS

2025 CX-50 Hybrid with VINS lower than 7MMVA*****124732 (produced before April 22, 2025)

DESCRIPTION

This technical service bulletin has been superseded to SSPE0.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.